

WATER LICENCE INSPECTION FORM

Original	
Follow-Up	Report

Licensee			Licensee Repres	Licensee Representative					
Sabina Gold a	nd Silver		Christian	Stand	dring				
Licence No. / Expiry			Representative's						
2AM-BRP1833	L		Environmental coordinator						
Land / Other Authorizat	ions		Land / Other Au	thorizatio	ons				
Date of Inspection	2022		Inspector	N 4 E C I	LED				
September 28	5, 2023		Jonathan	IVIESI	HEK				
Activities Inspected Camp Roads/Hauling	☐ Drilling ☐ Other:		Mining ☐ Construction ☐ Reclamation ☐ Fuel Storage ☐ Other:						
Conditions: A	- Acceptable	le C - Concern U - Unacceptable			NA – Not Appli	– Not Ins	pected		
Water Use	Condition (Comment Site Condition	S	Condit ion	Comme Haz/Mat	Management	Condition	Comment	
Intake/Screen	NA	Water Manage	ment Structures	NA	Storage		С		
Flow Measure. Dev	ice A	Culverts / Bridg	ges	Α	Spills		NA		
Source:	А	Drainage		NA	Spill Plan	CZ	NI		
Water Use:	А	Erosion / Sedir	nent	Α					
Recirculation (y /n)) NA	Mitigation Mea	asures	Α	Administ	trative			
		Reclamation A	ctivities	NA	Records		NI		
		Materials Stora	nge	NA	Reports		NI		
Waste Disposal		Signage			Plans		NI		
Waste Water	NA				Notificat	ions	А		
Solid Waste	A	Monitoring			Other				
Hazardous Waste	C	Sample Collect	ion / Analysis	Α	Follow-u	•	NI		
					previous	inspection			
	*The number i	in the comments field w	ill correspond with	n specif	ic comments prov	ided below.			
Samples taken by Ir	nspector:	Location(s):							
Yes No									
SECTION 1	Comments	s Non-	Compliance with	Act or	Licence	Action F	Required		
Background:						6			
On March 22,2023, I Jonathan Mesher of CIRNAC conducted inspections of Water Licence facilities under the licence 2AM-BRP1831 at MLA Camp. During this inspection I was accompanied by; Christian Standring (
		A Camp. During this	inspection I wa	as acco	ompanied by; C	hristian Sta	ndring (
B2Gold Employe	ee)								
Due to technical	i issues this re	eport is issued with	out photos.						
14/24221									
a. Water l									
	="	its fresh water from	n the ocean usi	ing a d	lesalination un	it located or	i a laydo	wn	
area	adjacent to B	athurst inlet.							
b. Waste 9	Storage								
	_	s inspaction (March	22 2022\ ;+	ac not	ad that multipl	o fuel table	for the d	iocol	
1. Ir	n the Previous	s inspection (March	-						
1. Ir h	n the Previous eaters were o	outside of containm	-						
1. Ir h	n the Previous eaters were o	· · · · · · · · · · · · · · · · · · ·	-						
1. Ir h	n the Previous eaters were c or these ment	outside of containm	ent, The licens	ee has	s since installed	l secondary	containı		
1. Ir h fo 2. D	n the Previous eaters were cor or these ment ouring the insp	outside of containm tioned fuel tanks.	ent, The licens	ee has see ha	s since installed	secondary waste cont	containi ainment	ment	
1. Ir h fo 2. D	the Previous eaters were cor or these ment ouring the inspacilities, one f	outside of containm tioned fuel tanks. pection it was noted	ent, The licens d that the licens and the secon	ee has see ha	s since installed as installed two a truck wash ar	secondary waste cont	containi ainment ntainmer	ment nt	
1. Ir h fo 2. D fa a	the Previous eaters were or or these ment during the insp acilities, one f reas are bene	outside of containm tioned fuel tanks. pection it was noted for hazardous waste	ent, The licens d that the licens and the secon preventing wa	ee has see ha id for a ste fro	s since installed as installed two a truck wash ar om contaminat	waste contact waste contact ea, both coi	containi ainment ntainmer ronment	ment nt	
1. Ir h fo 2. D fo a V	eaters were continued the previous or these ment ouring the inspacilities, one forces are beneaver	outside of containm tioned fuel tanks. pection it was noted or hazardous waste eficial to the site for	ent, The licens d that the licens and the secon preventing wa e I was unable t	see has d for a ste fro	s since installed as installed two a truck wash ar om contaminat	waste contact waste contact ea, both coi	containi ainment ntainmer ronment	ment nt	
1. Ir h fo 2. D fa a V	n the Previous eaters were continued the inspection of the inspection of the inspection of the inspection of the construction the construction the construction of the	outside of containm tioned fuel tanks. pection it was noted for hazardous waste eficial to the site for ng the NWB website	ent, The licens d that the licens and the secon preventing wa e I was unable t	see has see ha d for a ste fro to loca tures.	s since installed as installed two a truck wash ar om contaminat te the required	waste contacy waste contace ea, both coo ing the envi	containi ainment ntainmer ronment submissio	ment nt	
1. Ir h fo 2. D fa a V fo 3. N	the Previous eaters were cor these ment ouring the inspecialities, one forces are beneaville reviewing the construction to concerns were	outside of containmationed fuel tanks. pection it was noted for hazardous waster for hazardous waster for the NWB websiter for the site for high the NWB websiter for high the NWB websiter for the high the NWB websiter for the new for	ent, The licens I that the licens and the secon preventing wa I was unable to	see has see had d for a ste fro o loca tures.	s since installed two a truck wash arom contaminat te the required the bulk fuel c	waste contacy waste contace ea, both coo ing the envi	containi ainment ntainmer ronment submissio	ment nt	
1. Ir h fo	the Previous eaters were cor these ment ouring the inspecialities, one forces are beneaville reviewing the construction to concerns were	outside of containmationed fuel tanks. pection it was noted for hazardous waste afficial to the site for ng the NWB website action of waste markere noted regarding the and well kept a	ent, The licens I that the licens and the secon preventing wa I was unable to	see has d for a ste fro o loca tures. cion of	s since installed two a truck wash arom contaminat te the required the bulk fuel coection.	waste contacy waste contace ea, both coo ing the envi	containi ainment ntainmer ronment submissio area.	ment nt	



The licensee is to provide a plan 3 weeks after receiving the report to ensure the following concerns are addressed, this plan shall include a timeline for implementation.

1. The licensee is to provide the required submissions as described in Part D item 2 of the water licence 2AM-BRP1831 for the construction of the hazardous waste containment cell near MLA accommodations and the truck wash berms installed.

Inspector's Name	Licensee Representative's Name		
Jonathan MESHER	Merle Keefe		
Signature	Signature Liello		
Date	Date		
September 16, 2023	December 1, 2023		

Water Resource Officer, Nunavut Region Crown Indigenous Relations and Northern Affairs Canada - CIRNAC

Jonathan.mesher@canada.ca Office #: 867-222-0118

Fax: 867 979-6445

