

WATER LICENCE INSPECTION FORM

☒ Original

☐ Follow-Up Report

Licensee	Licensee Representative
Sabina Gold and Silver	Merle Keefe
Licence No. / Expiry	Representative's Title
2AM-BRP1831	Environmental permitting Manager
Land / Other Authorizations	Land / Other Authorizations
	--
Date of Inspection	Inspector
June 19, 2022	Jonathan MESHER
Activities Inspected	
<input checked="" type="checkbox"/> Camp	<input type="checkbox"/> Drilling
<input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Other:
<input checked="" type="checkbox"/> Mining	<input type="checkbox"/> Construction
	<input type="checkbox"/> Other:
	<input type="checkbox"/> Reclamation
	<input type="checkbox"/> Fuel Storage

Conditions:

A - Acceptable

C - Concern

U - Unacceptable

NA – Not Applicable


NI – Not Inspected

Water Use	Condition	Comment	Site Conditions	Condition	Comment	Haz/Mat Management	Condition	Comment
Intake/Screen	NA		Water Management Structures	NA		Storage	C	
Flow Measure. Device	NA		Culverts / Bridges	A		Spills	NA	
Source:	NA		Drainage	NA		Spill Plan	NI	
Water Use:	NA		Erosion / Sediment	C				
Recirculation ( y /n)	NA		Mitigation Measures	A		Administrative		
			Reclamation Activities	NA		Records	NI	
			Materials Storage	NA		Reports	NI	
Waste Disposal			Signage			Plans	NI	
Waste Water	NA					Notifications	A	
Solid Waste	A		Monitoring			Other		
Hazardous Waste	C		Sample Collection / Analysis	A		Follow-up from previous inspection	NI	
*The number in the comments field will correspond with specific comments provided below.								
Samples taken by Inspector:			Location(s):					
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No								


SECTION 1	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
<p>Background:</p> <p>On June 19,2022, I Jonathan Mesher conducted inspections of the following facilities under the licence 2AM-BRP1831; Goose Camp, Gorge Camp and the Marine Laydown Area. During this inspection I was accompanied by; Kelli Gillard (NIRB), Guillaume Daoust (NIRB) and Merle Keefe (Licensee).</p> <p>MLA Camp:</p> <p>a. <b>Waste Storage</b></p> <p>I. Hazardous Material Storage- The Freight Storage Laydown had 5 totes of Hazardous material outside of containment (see photo 1). On the Camp Laydown Pad there was multiple Barrels inside a single drip tray, potentially making it less than 110% of the largest container in the drip tray.(see photo 2) Part H, item 3,states; “The Licensee shall provide secondary containment for fuel and chemical storage as required by applicable standards and acceptable industry practice.”</p> <p>II. The licensee appears to be washing vehicles within 31m or ponding water, at the time of the inspection there appeared to be a visible sheen indicating hydrocarbons in the water. See photo 3 and 4 for the Pressure washer and potential oily sheen down gradient. Section 12(1) of the Nunavut Waters and Nunavut Surface Rights Tribunal Act states that; 12 (1) Subject to subsection (2) and except in accordance with the conditions of a licence, no person shall deposit or permit the deposit of waste (a) in waters in Nunavut; or (b) in any other place in Nunavut under conditions in which the waste, or any other waste that results from the deposit of that waste, may enter waters in Nunavut</p> <p>III. Behind the main camp there is a fuel tank without a drip tray, see photo 5 for fuel tank.</p> <p>IV. No concerns were noted regarding the bulk fuel storages.</p>			
Section 2	<input type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input checked="" type="checkbox"/> Action Required

**The licensee is to provide a plan 3 weeks after receiving the report to ensure the following concerns are addressed, this plan shall include a timeline for implementation.**

1. The licensee is to ensure all hazardous material is kept within secondary containment.
2. The licensee is to ensure no waste/water resulting from washing vehicles is enter water and/or causing erosion.
3. The inspector is recommending that licensee install drip trays below the fuel tank noted in a, III.

Inspector's Name	
Jonathan MESHER	
Signature	
	
Date	
July 15, 2022	

Water Resource Officer, Nunavut Region  
Crown Indigenous Relations and Northern Affairs Canada – CIRNAC  
Jonathan.mesher@canada.ca  
Office #: 867-975-4296  
Fax: 867 979-6445

Date	Camera	Inspector	Authorization
June 19, 2022	Sony Cyber-shot	J.Mesher	2AM-BRP
Photoba Log			
Photo 1			
			
Description: Hazardous material outside containment			



Date	Camera	Inspector	Authorization
June 19, 2022	Sony Cyber-shot	J.Mesher	2AM-BRP
Photo Log			
Photo 2			
			
Description: Drip trays with multiple barrels			

Date	Camera	Inspector	Authorization
June 19, 2022			
	Sony Cyber-shot	J.Mesher	2AM-BRP
Photo Log			
Photo 3			





Description: Pressure washer.

Date	Camera	Inspector	Authorization
June 19, 2022	Sony Cyber-shot	J.Mesher	2AM-BRP

Photo Log

Photo 4



Description: potential oily sheen.

Date	Camera	Inspector	Authorization
June 19, 2022			
	Sony Cyber-shot	J.Mesher	2AM-BRP

Photo Log





Photo 5



Description: Fuel tank without drip tray.