



Photos:

Top: Aerial photos of the North Dam

Photo 1a: View of the cracking observed on the upstream face pumping pad, looking east

Photo 1b, 1c: Two alternative photos of the cracking observed on the pumping pad

Photo 2: upstream face of the North Dam, looking west

		2018 Annual Geotechnical Inspection		
		North Dam Upstream Face		
Job No: 1CT022.028	Doris TIA	Date: January 2019	Approved: PL	Photolog: 1
Filename: 2018NDGeotechInsp_Rev1_sw.pptx				





Photos:  
 Photo 1: View of the North Dam crest, looking east  
 Photo 2: Views of the V-notch weir installed at the downstream toe of the North Dam in 2018  
 Photo 3: Close-up of the V-notch weir installed at the downstream toe  
 Middle: Aerial photo of the North Dam

		2018 Annual Geotechnical Inspection		
		North Dam Downstream Face		
Job No: 1CT022.028	Doris TIA	Date: January 2019	Approved: PL	Photolog: 2
Filename: 2018NDGeotechInsp_Rev1_sw.pptx				