



Photos:

- Photo 1: Photo of the TIA with the primary spigot points and the overburden dump
- Photo 2: East shoreline of the TIA in 2017, prior to the construction of the South Dam
- Photo 3: Northern spigot point on the east side of the TIA
- Photo 4: View of the South Dam and southern shoreline looking north

		2018 Annual Geotechnical Inspection		
		TIA Shoreline and Tailings Deposition (South End)		
Job No: 1CT022.028	Doris TIA	Date: January 2019	Approved: PL	Photolog: 6
Filename: 2018NDGeotechInsp_Rev1_sw.pptx				



Photos:
 Photo 1: Photo of North EDCB looking south
 Photo 2: Photo of the North EDCB looking NE
 Photo 3: South EDCB looking south,
 Photo 4: South EDCB looking SE
 Photo 5: South EDCB looking east over Doris Lake

		2018 Annual Geotechnical Inspection		
		Emergency Dump Catch Basins		
Job No: 1CT022.028 Filename: 2018NDGeotechInsp_Rev1_sw.pptx	Doris TIA	Date: January 2019	Approved: PL	Photolog: 7



Photos:

Photo 1: TIA Reclaim pipeline

Photo 2: Tailings discharge and reclaim pipeline passing the South Emergency Dump Catch Basin (EDCB)

Photo 3: Tailings pipeline and electrical cable on tundra between Doris Camp and the TIA

Photo 4: Tailings pipeline crossing the Doris Creek Bridge

		2018 Annual Geotechnical Inspection		
		Tailings Discharge and Reclaim Pipeline (Near TIA)		
Job No: 1CT022.028	Doris TIA	Date: January 2019	Approved: PL	Photolog: 8
Filename: 2018NDGeotechInsp_Rev1_sw.pptx				