

Appendix F: Weekly Monitoring Reports



North Dam Weekly Walkover Survey Report

Date:	JUNE 7, 2014
Inspected By:	IKEY EVALIK
Conditions:	(ie. snow on ground, clear)

Visual Inspection:

This weekly walkover survey report is a means to track the condition on the North Dam, please provide details on changes that have developed since the previous inspection and/or any observations of particular concern. All photos are appreciated. Please send the completed form (scans are fine) and any photos to hopebaymonitoring@srk.com and mmiller@srk.com

Upstream Side of Dam		
Any visible concerns? (cracks, depressions, erosion, etc.)	Yes	No (1)
Downstream Side of Dam		
Any visible concerns? (cracks, depressions, erosion, seepage, etc.)	Yes (2)	No
Crest of Dam		
Any visible concerns? (cracks, depressions, erosion, etc.)	Yes	No
Thermosyphons North Side		
Any visible concerns? (cracks, punctures, peeling paint, birds nests, etc.)	Yes	No (3)
Thermosyphons South Side		
Any visible concerns? (cracks, punctures, peeling paint, birds nests, etc.)	Yes	No
Instrumentation (on crest and downstream side)		
Any visible concerns? (bent, rusted, cracked, etc.)	Yes	No
Thermistors and Dataloggers		
Any visible concerns? (frayed or cut cables, damaged boxes, etc.)	Yes	No (4)
If you answered yes to any of the questions above please provide details and photos. Observations can be sketched on the figure provided on the next page. If seepage has been noted please estimate the flow.		
(1) Partially covered with snow		
(2) ^{small} Depression/erosion - midway - pictures taken ND-DSP-100 (WEST)		
(3) WILDLIFE PAW SCRATCH MARKS ON PAINT - FURTHEST EAST.		
(4) TOOK PICTURE OF STRUG 21 ON TEMPORARY REPAIR DONE		

Please collect the following photos:

- Photo from north end looking south along the dam
- Photo from south end looking north along the dam

North Dam Weekly Monitoring





North Dam Weekly Walkover Survey Report


Date:	June 14/14
Inspected By:	Ikey & Jill
Conditions:	(ie. snow on ground, clear) Clear, w/ snow on upstream & downstream toes

Visual Inspection:

This weekly walkover survey report is a means to track the condition on the North Dam, please provide details on changes that have developed since the previous inspection and/or any observations of particular concern. All photos are appreciated. Please send the completed form (scans are fine) and any photos to hosebaymonitoring@ark.com and mmiller@ark.com

Upstream Side of Dam	
Any visible concerns? (cracks, depressions, erosion, etc.)	Yes <input type="radio"/> No <input checked="" type="radio"/>
Downstream Side of Dam	
Any visible concerns? (cracks, depressions, erosion, seepage, etc.)	Yes <input checked="" type="radio"/> ³ <input checked="" type="radio"/> ¹ <input checked="" type="radio"/> ² No <input type="radio"/>
Crest of Dam	
Any visible concerns? (cracks, depressions, erosion, etc.)	Yes <input type="radio"/> No <input checked="" type="radio"/>
Thermosyphons North Side	
Any visible concerns? (cracks, punctures, peeling paint, birds nests, etc.)	Yes <input type="radio"/> No <input checked="" type="radio"/>
Thermosyphons South Side	
Any visible concerns? (cracks, punctures, peeling paint, birds nests, etc.)	Yes <input type="radio"/> No <input checked="" type="radio"/>
Instrumentation (on crest and downstream side)	
Any visible concerns? (bent, rusted, cracked, etc.)	Yes <input type="radio"/> No <input checked="" type="radio"/>
Thermistors and Dataloggers	
Any visible concerns? (frayed or cut cables, damaged boxes, etc.)	Yes <input type="radio"/> No <input type="radio"/>
<p>If you answered yes to any of the questions above please provide details and photos. Observations can be sketched on the figure provided on the next page. If seepage has been noted please estimate the flow.</p> <p>① Possible Fox den ~ 15 ft NW of ND-120-3 (see pic)</p> <p>② Several smaller depressions on DS side, one larger: 5' x 5' w ~ 1' deep. ND-SW-070-3 (see pic)</p> <p>③ Snow melt creating a small trickle of water ENE of South Thermosyphons - should disappear when snow is gone. (see pic)</p>	

Please provide any other observations you have made or items that did not fit in the space above



Photos:

Please collect the following photos:

Photo from north end looking south along the dam



Photo from south end looking north along the dam



Other photos, please describe (1), (2), (3)