

















## North Dam Weekly Walkover Survey Report

Date:	21 June 14
Inspected By:	Jill/Branden
Conditions:	(ie. snow on ground, clear) Clear/Small Patch snow @ downstream toe

### Visual Inspection:

This weekly walkover survey report is a means to track the condition on the North Dam, please provide details on changes that have developed since the previous inspection and/or any observations of particular concern. All photos are appreciated. Please send the completed form (scans are fine) and any photos to [hopebaymonitoring@srk.com](mailto:hopebaymonitoring@srk.com) and [mmiller@srk.com](mailto:mmiller@srk.com)

#### Upstream Side of Dam

Any visible concerns? (cracks, depressions, erosion, etc.)

Yes

No

①

#### Downstream Side of Dam

Any visible concerns? (cracks, depressions, erosion, seepage, etc.)

Yes

No

#### Crest of Dam

Any visible concerns? (cracks, depressions, erosion, etc.)

Yes

No

#### Thermosyphons North Side

Any visible concerns? (cracks, punctures, peeling paint, birds nests, etc.)

Yes

No

#### Thermosyphons South Side

Any visible concerns? (cracks, punctures, peeling paint, birds nests, etc.)

Yes

No

#### Instrumentation (on crest and downstream side)

Any visible concerns? (bent, rusted, cracked, etc.)

Yes

No

#### Thermistors and Dataloggers

Any visible concerns? (frayed or cut cables, damaged boxes, etc.)

Yes

No

If you answered yes to any of the questions above please provide details and photos. Observations can be sketched on the figure provided on the next page. If seepage has been noted please estimate the flow.

Check for suspended sediment @ TIA: None

① Pretty crude rock, uneven across an area 20ft x 10ft on downstream side (see 2 pics)