

# North Dam Weekly Walkover Survey Report

Date:	MARCH 22, 2015
Inspected By:	Scott Grubbs
Conditions:	(ie. snow on ground, clear) SNOW ON GROUND.


## Visual Inspection:

This weekly walkover survey report is a means to track the condition on the North Dam, please provide details on changes that have developed since the previous inspection and/or any observations of particular concern. All photos are appreciated. Please send the completed form (scans are fine) and any photos to [hopebaymonitoring@srk.com](mailto:hopebaymonitoring@srk.com) and [pluedke@srk.com](mailto:pluedke@srk.com)

<b>Upstream Side of Dam</b>		
Any visible concerns? (cracks, depressions, erosion, etc.)	Yes	No
<b>Downstream Side of Dam</b>		
Any visible concerns? (cracks, depressions, erosion, seepage, etc.)	Yes	No
<b>Crest of Dam</b>		
Any visible concerns? (cracks, depressions, erosion, etc.)	Yes	No
<b>Thermosyphons North Side</b>		
Any visible concerns? (cracks, punctures, peeling paint, birds nests, etc.)	Yes	No
<b>Thermosyphons South Side</b>		
Any visible concerns? (cracks, punctures, peeling paint, birds nests, etc.)	Yes	No
<b>Instrumentation (on crest and downstream side)</b>		
Any visible concerns? (bent, rusted, cracked, etc.)	Yes	No
<b>Thermistors and Dataloggers</b>		
Any visible concerns? (frayed or cut cables, damaged boxes, etc.)	Yes	No
<b>Suspended Sediment in TIA (When not frozen)</b>		
Any suspended sediment in Tail Lake?	Yes	No
<p>If you answered yes to any of the questions above please provide details and photos. Observations can be sketched on the figure provided on the next page. If seepage has been noted please estimate the flow.</p>		
<p>Photo:   Photo from north end looking south along the dam   Photo from south end looking north along the dam   Photo: Please describe</p>		



Please provide any other observations you have made or items that did not fit in the space above



**Photos:**

Please collect the following photos:

Photo from north end looking south along the dam

Photo from south end looking north along the dam

☐

☒


Other photos, please describe

MARCH 22, 2015

Rev. 20141113







Date:	MARCH 27, 2015
Inspected By:	DAVE SHERLOCK
Conditions:	(ie. snow on ground, clear) SNOW ON GROUND

### Visual Inspection:

This weekly walkover survey report is a means to track the condition on the North Dam, please provide details on changes that have developed since the previous inspection and/or any observations of particular concern. All photos are appreciated. Please send the completed form (scans are fine) and any photos to [hopebaymonitoring@srk.com](mailto:hopebaymonitoring@srk.com) and [pluedke@srk.com](mailto:pluedke@srk.com)

<b>Upstream Side of Dam</b>		
Any visible concerns? (cracks, depressions, erosion, etc.)	Yes	No
<b>Downstream Side of Dam</b>		
Any visible concerns? (cracks, depressions, erosion, seepage, etc.)	Yes	No
<b>Crest of Dam</b>		
Any visible concerns? (cracks, depressions, erosion, etc.)	Yes	No
<b>Thermosyphons North Side</b>		
Any visible concerns? (cracks, punctures, peeling paint, birds nests, etc.)	Yes	No
<b>Thermosyphons South Side</b>		
Any visible concerns? (cracks, punctures, peeling paint, birds nests, etc.)	Yes	No
<b>Instrumentation (on crest and downstream side)</b>		
Any visible concerns? (bent, rusted, cracked, etc.)	Yes	No
<b>Thermistors and Dataloggers</b>		
Any visible concerns? (frayed or cut cables, damaged boxes, etc.)	Yes	No
<b>Suspended Sediment in TIA (When not frozen)</b>		
Any suspended sediment in Tail Lake?	Yes	No
<p>If you answered yes to any of the questions above please provide details and photos. Observations can be sketched on the figure provided on the next page. If seepage has been noted please estimate the flow.</p>		



Please provide any other observations you have made or items that did not fit in the space above



**Photos:**

Please collect the following photos:

Photo from north end looking south along the dam



Photo from south end looking north along the dam



Other photos, please describe