

Photos:

Please collect the following photos:	P	
Photo from north end looking south along the dam Photo from south end looking north along the dam	5/	
Other photos, please describe		












North Dam Weekly Walkover Survey Report

Date:	NOVEMBER 1, 2014		
nspected By:	IKEY EVALIR & ANDY TO	PLAK	
Conditions:	(ie. snow on ground, clear) MESTLY CLOUDY, DRIFTING SABO	From West	
leveloped since the	etion: er survey report is a means to track the condition on the North Dam, place previous inspection and/or any observations of particular concern. All ans are fine) and any photos to hopebaymonitoring@srk.com and mmileostrum .	i priotos are appreciat	on changes that have ted. Please send the
Upstream Sid Any visible cor	e of Dam ncerns? (cracks, depressions, erosion, etc.)	Yes	No No
Downstream Any visible cor	Side of Dam ncerns? (cracks, depressions, erosion, seepage, etc.)	Yes	2). No
Crest of Dam Any visible cor	ncerns? (cracks, depressions, erosion, etc.)	Yes	No
	ons North Side ncerns? (cracks, punctures, peeling paint, birds nests, etc.)	Yes	No
***	ons South Side ncerns? (cracks, punctures, peeling paint, birds nests, etc.)	Yes	No
	ncerns? (bent, rusted, cracked, etc.)	Yes	No
Any visible co	and Dataloggers ncerns? (frayed or cut cables, damaged boxes, etc.)	Yes	No
Check f	res to any of the questions above please provide details and photos. Onext page. If seepage has been noted please estimate the flow. EN SUSPENDED THEN THE PREVIOUS SURVE E DEEPER SNOW THEN THE PREVIOUS SURVE E DEEPER SNOW THEN THE PREVIOUS	EY	



Photos:

