


C:\01_SITES\Hope Bay\North Dam\2016 Annual Inspection\1CT022.009-North Dam Typical Sections 2016.dwg





Crest of the North Dam looking southwest from Station 0+140.



Pump and access road along south side of the upstream face of the North Dam.



Downstream face of the North Dam looking northeast from Station 0+010.



Centerline of the North Dam, looking northeast from Station 0+010.



Depression on downstream face of the North Dam, paint markings show limited expansion from previous inspections.

		2016 Geotechnical Inspection		
		North Dam Downstream Face		
Job No: 1CT022.009	Doris Mine	Date: March 2017	Approved: PL	Figure: 6
Filename: 2016GeotechInsp_20170321.pptx				