




Work Area	Facility	WBS Code
Tailings Impoundment Area	North Dam	TIA-001
	South Dam	TIA-002
	Interim Dyke	TIA-003
	Sub-aerial Tailings	TIA-004
	Shoreline Protection	TIA-005
Quarry #3	Quarry #3	Q3-001
	Quarry #3 Access Road	Q3-002
	Quarry #3 Landfill	Q3-003
Secondary Road Area	Secondary Road	SR-001
	Tailings and Reclaim Water Pipelines	SR-002
	Tail Lake Access Road (Chainage 0+725 of Secondary Rd)	SR-003
	Explosive Facility	SR-004



SRK JOB NO.: 1CT022.002.200.2100
FILE NAME: 1CT022.000_TailLake_Rev2.dwg




TMAC Resources Inc.

Interim Closure and Reclamation Plan


Tailings Impoundment Area
Work Breakdown Structure

DATE: May 2015 APPROVED: IM FIGURE: 11

C:\01_SITES\Hope Bay\Doris North\Closure\1CT022.000_TailLake_Rev2.dwg



Aerial Photo circa Sept. 2007



SRK JOB NO.: 1CT022.002.200.2100
FILE NAME: 1CT022.000_TailLake_Rev2.dwg



TMAC Resources Inc.

Interim Closure and Reclamation Plan

Tailings Impoundment Area
Terrain Configuration Before Construction

DATE: May 2015	APPROVED: IM	FIGURE: 12
-------------------	-----------------	---------------

Task Name		Year -1 (2021)			Year 1 (2022)				Year 2 (2023)				Year 3 (2024)				Year 4 (2025)				Year 5 (2026)				Year 6 (2027)				Year 7 (2028)				Year 8 (2029)				Year 9 (2030)				Year 10 (2031)				Year 11 (2032)							
		Q2	Q3	Q4	Q1	Q2	Q3	Q4	Q1	Q2	Q3	Q4	Q1	Q2	Q3	Q4	Q1	Q2	Q3	Q4	Q1	Q2	Q3	Q4	Q1	Q2	Q3	Q4	Q1	Q2	Q3	Q4	Q1	Q2	Q3	Q4	Q1	Q2	Q3	Q4	Q1	Q2	Q3	Q4								
Completion of Project		♦ Completion of Production																																																		
Decommissioning & closure																																																				
Water Management																																																				
Post Closure Monitoring	Covers Monitoring																																																			
	Geotechnical Inspection																																																			
	Water Quality Monitoring																																																			