




Figure A10
Stability Analysis - Downstream, Rapid Drawdown - Rotational Slip Surface




Figure A11
Stability Analysis - Downstream, Seismic - Rotational Slip Surface




Figure A12
Stability Analysis - Downstream, End of Construction - Rotational Slip Surface




Figure A13
Stability Analysis - Downstream, Static Analysis - Slip Surface along Liner




Figure A14
Stability Analysis - Downstream, Seismic Analysis - Slip Surface along Liner




Figure A15
Stability Analysis - Downstream, End of Construction - Slip Surface along Liner





Figure A16
Stability Analysis - Full Tailings - Overall Stability - Ice Rich Foundation



Stability Analysis - Downstream, Full Tailings -Overall Stability - Ice Poor Foundation