

Lupin Mines Incorporated
(a subsidiary of Elgin Mining Inc.)

Nov 15 2012

Ms. Phyllis Beaulieu
Manager of Licensing
Nunavut Water Board
P.O. Box 119
Gjoa Haven, NU
X0B 1J0

Dear Ms. Beaulieu

**RE: 2012 Annual Geotechnical Inspection-Lupin Mine Tailings Containment Area, Nunavut
Lupin Mine Inc, Nunavut, License Number 2AM-LUP0914**

Please see the attached 2012 Geotechnical inspection report to fulfil Part E, Item 6 (g) of our Water Licence.


The "General Recommendations" from the 2012 Geotechnical Report (Section 4.2) described the need to address some maintenance issues, as well as structural issues of Dam M. These concerns have been addressed in the recently submitted draft "Plan for Compliance", Section "E, 6 (d) Operation and maintenance of the tailings containment facility-Erosion".

Similarly, the suggestion from the "General Recommendations" from the 2012 Geotechnical Report (Section 4.2) to revise the monitoring schedule has been addressed in the draft "Plan for Compliance", Section "E, 6(f) Operation and maintenance of the tailings containment facility-Inspection Frequency".

If you have any questions regarding the above, please do not hesitate to contact me.

Sincerely,

Lupin Mines Incorporated.



James A. (Jim) Currie
COO