



Photo 17 shows a view of the crest looking towards the south abutment.



Photo 19 shows a view of the riprap on the upstream side. The distance from the water level to the crest of this dam is approximately 3.5 metres.



Photo 23 shows the alternating colour pattern of the dark grey angular rock over top of the light brown esker sand and gravel on the downstream slope.




Photo 27 shows some longitudinal cracks formed in the angular rock fill. These cracks were previously noted proximal to the valve locations.

CLIENT:



AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA STATEMENTS CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.

-	-	-	-	-	-
-	-	-	-	-	-
-	-	-	-	-	-
REV.	DATE	REVISION NOTES	DRAWN	CHECKED	APPROVED

SCALE:	N/A	
DATE:	September 2003	
DRAWN:	SLF	
DESIGNED:	JWC	
CHECKED:	JWC	
APPROVED:	JWC	

PROJECT ANNUAL INSPECTION OF PERIMETER TAILINGS DAMS		
TITLE DAM 1A INSPECTION PHOTOS		
PROJECT No.	DWG. No.	REV.
0256-009-02	5	0