



Photo 29 is a view of the crest on the upstream side. As previously noted, the riprap on the upstream side is relatively undulating. This dam does not currently retain any water.



Photo 31 is a view of the crest on the upstream side again looking towards the north.

AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA STATEMENTS CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.

SCALE:	N/A	DESIGNED:	JWC
DATE:	Oct 2004	CHECKED:	JWC
DRAWN:	SLF	APPROVED:	JWC

CLIENT:

KINROSS
Gold Corporation

BGC

BGC Engineering Inc.
AN APPLIED EARTH SCIENCES COMPANY

Calgary, Alberta.

Phone: (403) 250-5185

PROJECT ANNUAL INSPECTION OF PERIMETER TAILINGS DAMS		
TITLE DAM 1B INSPECTION PHOTOS		
PROJECT No. 0256-009-02	DWG. No. 6	REV. 0