



Photo 35 shows the upstream side and the crest. We do have a slight undulating nature to the riprap, likely a result of construction traffic activity.



Photo 38 is a view along the access road toe berm. The downstream side has no signs of deformation or cracking from this perspective.

AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA STATEMENTS CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.

SCALE:	N/A	DESIGNED:	JWC
DATE:	Oct 2004	CHECKED:	JWC
DRAWN:	SLF	APPROVED:	JWC

CLIENT: **KINROSS**
Gold Corporation



BGC Engineering Inc.
AN APPLIED EARTH SCIENCES COMPANY

Calgary, Alberta.

Phone: (403) 250-5185

PROJECT ANNUAL INSPECTION OF PERIMETER TAILINGS DAMS		
TITLE DAM 1C INSPECTION PHOTOS		
PROJECT No. 0256-009-02	DWG. No. 7	REV. 0