



Photo 2 shows a view of the upstream side. The condition of the riprap appears to be satisfactory.



Photo 4 is a view of the upstream side. The distance from the current pond level to the crest is approximately 3.5 metres. Occasional small scarp form at the water level.



Photo 3 shows the condition of the crest looking towards the south. From this perspective, there are no signs of settlement or cracking.



Photo 8 is just another view of the downstream face.

CLIENT:



AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA STATEMENTS CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.

-	-	-	-	-	-
-	-	-	-	-	-
-	-	-	-	-	-
REV.	DATE	REVISION NOTES	DRAWN	CHECKED	APPROVED

SCALE:	N/A	
DATE:	October 2004	
DRAWN:	SLF	
DESIGNED:	JWC	
CHECKED:	JWC	
APPROVED:	JWC	

PROJECT    ANNUAL INSPECTION OF PERIMETER TAILINGS DAMS		
TITLE    DAM 2 INSPECTION PHOTOS		
PROJECT No.	DWG. No.	REV.
0256-009-02	8	0