



Photo 72 shows a view of Dam 3 with Boomerang Lake on the left.



Photo 79 shows a small ditch which runs from the south end towards the north and then bends 90 degrees to the east across the crest of this dam. It is used to direct some of the surficial drainage and from this perspective, looks in satisfactory condition.



Photo 73 shows the toe edge where it meets Boomerang Lake. This is the area where historically cracking has been seen, No significant sloughs are noted right now.



Photo 80 shows the condition of Dam 3 looking towards the north along the toe of this dam. There are no signs of significant erosion or any seepage discharging from this reclaimed dam.

CLIENT:



AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA STATEMENTS CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.

-	-	-	-	-	-
-	-	-	-	-	-
-	-	-	-	-	-
REV.	DATE	REVISION NOTES	DRAWN	CHECKED	APPROVED

SCALE:	N/A	
DATE:	October 2004	
DRAWN:	SLF	
DESIGNED:	JWC	
CHECKED:	JWC	
APPROVED:	JWC	

PROJECT	ANNUAL INSPECTION OF PERIMETER TAILINGS DAMS		
TITLE	DAM 3 INSPECTION PHOTOS		
PROJECT No.	DWG. No.	REV.	
0256-009-02	9	0	



BGC Engineering Inc.
AN APPLIED EARTH SCIENCES COMPANY

Calgary Alberta

Phone: (403) 250-5185