



Photo 54 shows the crest of this dam and the downstream side. Windrows have been formed by recent grading activity for vehicle access.



Photo 56 shows the view of the downstream face on the crest.

AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA STATEMENTS CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.

SCALE:	N/A	DESIGNED:	JWC
DATE:	Oct 2004	CHECKED:	JWC
DRAWN:	SLF	APPROVED:	JWC

CLIENT: **KINROSS**
Gold Corporation



BGC Engineering Inc.
AN APPLIED EARTH SCIENCES COMPANY

Calgary, Alberta.

Phone: (403) 250-5185

PROJECT ANNUAL INSPECTION OF PERIMETER TAILINGS DAMS		
TITLE DAM 5 INSPECTION PHOTOS		
PROJECT No. 0256-009-02	DWG. No. 11	REV. 0