

APPENDIX A

PHOTOGRAPHS

PART

OF

CLOSURE PLAN FOR

TAILINGS CONTAINMENT AREA

Prepared for

Kinross Gold Corporation

LUPIN OPERATION

LIST OF PHOTOS

Photo 1. Lupin tailings containment area, 2001	1
Photo 2. Looking north toward plant; Cell 5 in foreground and Cell 2 to the right	2
Photo 3. Cells 2 and 1 adjacent to Pond 1 in foreground.....	2
Photo 4. Looking southwest with Cell 3 bounded by Dams K & L and J Dam in lower left	3
Photo 5. Looking east with N Dam to the right and M Dam to the left.....	3
Photo 6. Dam 1a looking north.....	4
Photo 7. Dam 2 looking south.....	4
Photo 8. Dam 4 looking northeast, TCA on left	5
Photo 9. Dam 3D, looking west, Cell 1 to the right (not visible)	5
Photo 10. K Dam, looking northeast; Pond 2 to the left	6
Photo 11. M Dam, looking east with Pond 2 to the right.....	6
Photo 12. Tailings being covered with esker	7
Photo 13. Test pit excavations, September 2004	7
Photo 14. Test pit 1-1 in Cell 1, located at new pipe 7 installation	7
Photo 15. Test pit 1-2, in Cell 1, located at Pipe 1 location. Pipe removed and place in Cell 3.....	7
Photo 16. Test Pit 1-3 at test pad, south, excavation for pipe repositioning.....	8
Photo 17. Test Pit 1-3 at test pad, south, new pipe being backfilled	8
Photo 18. Test pit 1a-1 in Cell 1a; note coarser esker and wet base.....	8
Photo 19. Test pit 2-1 in northern section of Cell 2 with older tailings,; minor oxidation at tailings surface	8
Photo 20. Test Pit 2-2 in southern area of Cell 2	9
Photo 21. Test pit 2-3, in southern area of Cell 2, closer to mid point of cell.....	9
Photo 22. Test pit 3-1 in Cell 3. Minor oxidation of tailings. This part of cell was covered only weeks earlier.	9
Photo 23. Test pit 3b-1 in Cell 3b.....	9



Photo 1. Lupin tailings containment area, 2001



Photo 2. Looking north toward plant; Cell 5 in foreground and Cell 2 to the right



Photo 3. Cells 2 and 1 adjacent to Pond 1 in foreground



Photo 4. Looking southwest with Cell 3 bounded by Dams K & L and J Dam in lower left



Photo 5. Looking east with N Dam to the right and M Dam to the left



Photo 6. Dam 1a looking north



Photo 7. Dam 2 looking south



Photo 8. Dam 4 looking northeast, TCA on left



Photo 9. Dam 3D, looking west, Cell 1 to the right (not visible)



Photo 10, K Dam, looking northeast; Pond 2 to the left



Photo 11. M Dam, looking east with Pond 2 to the right



Photo 12. Tailings being covered with esker



Photo 13. Test pit excavations, September 2004



Photo 14. Test pit 1-1 in Cell 1, located at new pipe 7 installation



Photo 15. Test pit 1-2, in Cell 1, located at Pipe 1 location. Pipe removed and place in Cell 3



Photo 16. Test Pit 1-3 at test pad, south, excavation for pipe repositioning



Photo 17. Test Pit 1-3 at test pad, south, new pipe being backfilled



Photo 18. Test pit 1a-1 in Cell 1a; note coarser esker and wet base



Photo 19. Test pit 2-1 in northern section of Cell 2 with older tailings; minor oxidation at tailings surface



Photo 20. Test Pit 2-2 in southern area of Cell 2



Photo 21. Test pit 2-3, in southern area of Cell 2, closer to mid point of cell



Photo 22. Test pit 3-1 in Cell 3. Minor oxidation of tailings. This part of cell was covered only weeks earlier.



Photo 23. Test pit 3b-1 in Cell 3b.