



Photo shows the crest of Dam 1A looking towards its south abutment.



Photo shows the downstream side.



Photo shows the pond on the upstream side of Dam 1A. At the current time, the distance from the head pond to the physical crest is approximately 4.5 m.



Photo shows the steep face overlooking the valves which come from the discharge pipes. The rockfill slope is oversteepened and there are some longitudinal cracks.

CLIENT:



AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA STATEMENTS CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.

-	-	-	-	-	-
-	-	-	-	-	-
-	-	-	-	-	-
REV.	DATE	REVISION NOTES	DRAWN	CHECKED	APPROVED

SCALE:	N/A	
DATE:	September 2005	
DRAWN:	SLF	
DESIGNED:	JWC	
CHECKED:	JWC	
APPROVED:	JWC	

PROJECT ANNUAL INSPECTION OF PERIMETER TAILINGS DAMS		
TITLE DAM 1A INSPECTION PHOTOS		
PROJECT No. 0256-011-01	FIGURE No. 5	REV. 0



BGC Engineering Inc.
AN APPLIED EARTH SCIENCES COMPANY

Calgary Alberta

Phone: (403) 250-5185