



Photo shows the upstream side and crest of this dam. This dam does not retain any water at the current time.



Photo shows the upstream side. No observations of settlement or cracking were noted.

AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA STATEMENTS CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.

SCALE:	N/A	DESIGNED:	JWC
DATE:	SEPT 2005	CHECKED:	JWC
DRAWN:	SLF	APPROVED:	JWC

CLIENT: **KINROSS**
Gold Corporation



BGC Engineering Inc.
AN APPLIED EARTH SCIENCES COMPANY

Calgary, Alberta.

Phone: (403) 250-5185

PROJECT ANNUAL INSPECTION OF PERIMETER TAILINGS DAMS		
TITLE DAM 1B INSPECTION PHOTOS		
PROJECT No. 0256-011-01	FIGURE No. 6	REV. 0