



Photo shows the crest on the upstream side looking in the southern direction. There are several small ponds located on the upstream side but no continuous head pond of water is actually retained against this dam currently.



Photo shows the downstream toe. There are no signs of cracking, settlement or seepage.

AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA STATEMENTS CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.

SCALE:	N/A	DESIGNED:	JWC
DATE:	SEPT 2005	CHECKED:	JWC
DRAWN:	SLF	APPROVED:	JWC

CLIENT: **KINROSS**  
Gold Corporation



**BGC Engineering Inc.**  
AN APPLIED EARTH SCIENCES COMPANY

Calgary, Alberta.

Phone: (403) 250-5185

PROJECT <b>ANNUAL INSPECTION OF PERIMETER TAILINGS DAMS</b>		
TITLE <b>DAM 1C INSPECTION PHOTOS</b>		
PROJECT No. <b>0256-011-01</b>	FIGURE No. <b>7</b>	REV. <b>0</b>