



Photo shows the crest on the downstream side. This dam does not retain any solids or water at the current time.



Photo shows the downstream slope of this dam. No signs of erosion or seepage noted from this perspective.

AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA STATEMENTS CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.

SCALE:	N/A	DESIGNED:	JWC
DATE:	SEPT 2005	CHECKED:	JWC
DRAWN:	SLF	APPROVED:	JWC

CLIENT:

**KINROSS**  
Gold Corporation

**BGC**

**BGC Engineering Inc.**  
AN APPLIED EARTH SCIENCES COMPANY

Calgary, Alberta.

Phone: (403) 250-5185

PROJECT **ANNUAL INSPECTION OF PERIMETER  
TAILINGS DAMS**

TITLE **DAM 5 INSPECTION PHOTOS**

PROJECT No.	FIGURE No.	REV.
0256-011-01	11	0