



AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA STATEMENTS CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.




View of the upstream side and crest. It should be noted that this pond does not retain a head of water. The crest appears consistent with no signs of deformations.



Shows the crest and the upstream side towards the south abutment.




View of the crest and the upstream side looking towards it south abutment. This dam has no retained head pond and only a few small isolated ponds of water are retained by this dam.



Shows the crest and upstream side and the small isolated pond.



Shows some longitudinal cracks in the riprap on the upstream side.



Shows the downstream edge of this dam. No significant concerns are expressed.

CLIENT:



REV	DATE	REVISION NOTES	DRAWN	CHECKED	APPROVED
-	-	-	-	-	-
-	-	-	-	-	-
-	-	-	-	-	-

AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA STATEMENTS CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.

SCALE:	N/A
DATE:	OCTOBER 2006
DRAWN:	SLF
DESIGNED:	JWC
CHECKED:	JWC
APPROVED:	JWC

PROJECT	ANNUAL INSPECTION OF PERIMETER TAILINGS DAMS
TITLE	DAM 1C INSPECTION PHOTOS
PROJECT No.	0256-012-01
FIGURE No.	7
REV	0