

PROJECT		ANNUAL INSPECTION OF PERIMETER TAILINGS DAMS		TITLE	
DAM 2 INSPECTION PHOTOS					
PROJECT NO.		FIGURE NO.		REV.	
0256-012-01		8		0	


SCALE:	N/A
DATE:	OCTOBER 2006
DRAWN:	SLF
DESIGNED:	JWC
CHECKED:	JWC
APPROVED:	JWC



REV	DATE	REVISION NOTES	DRAWN	CHECKED	APPROVED
1	2	1	1	1	1
1	1	1	1	1	1
	1	1		1	1

AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA STATEMENTS CONCLUSIONS OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL.


CLIENT:




Shows the upstream side located approximately 1 m above the existing pond level.




Shows an upstream side of Dam 2.





Shows the access road and toe berm located right at the toe of the downstream face.



View of the crest looking towards the southwest. No signs of settlement from this location.





CLIENT:			
ANNUAL INSPECTION OF PERIMETER TAILINGS DAMS DAM 3 INSPECTION PHOTOS PROJECT NO. 0256-012-01 FIGURE NO. 9 REV. 0			
PROJECT		TITLE	
ANNUAL INSPECTION OF PERIMETER TAILINGS DAMS		DAM 3 INSPECTION PHOTOS	
PROJECT NO. 0256-012-01		FIGURE NO. 9 REV. 0	
BGC Engineering Inc. AN APPLIED EARTH SCIENCES COMPANY Calgary Alberta Phone: (403) 250-5185			