





Shows a view of Dam #6 looking towards its south abutment. At the current time, there is no standing water retained by this dam.



Shows the crest and downstream toe looking towards its north end.



Shows some longitudinal cracks within the fill material located in the berm.



Shows longitudinal cracks located at the downstream toe of the fill.


CLIENT



AS A MUTUAL PROTECTION TO OUR CLIENT, THE PUBLIC AND OURSELVES, ALL REPORTS AND DRAWINGS ARE SUBMITTED FOR THE CONFIDENTIAL INFORMATION OF OUR CLIENT AND DRAWINGS ARE SUBMITTED FOR USE AND/OR PUBLICATION OF DATA FOR A SPECIFIC PROJECT AND AUTHORIZATION FOR USE AND/OR PUBLICATION OF DATA STATEMENTS CONCLUDES OR ABSTRACTS FROM OR REGARDING OUR REPORTS AND DRAWINGS IS RESERVED PENDING OUR WRITTEN APPROVAL

REV	DATE	REVISION NOTES	DRAWN	CHECKED	APPROVED
-	-	-	-	-	-
-	-	-	-	-	-
-	-	-	-	-	-

SCALE:	N/A
DATE:	OCTOBER 2006
DRAWN:	SLF
DESIGNED:	JWC
CHECKED:	JWC
APPROVED:	JWC



PROJECT	ANNUAL INSPECTION OF PERIMETER TAILINGS DAMS
TITLE	DAM 6 INSPECTION PHOTOS
PROJECT No.	0256-012-01
FIGURE No.	12
REV	0