Lupin Mines Incorporated

(a subsidiary of Elgin Mining Inc.)

5 November 2013

Ms. Phyllis Beaulieu Manager of Licensing Nunavut Water Board P.O. Box 119 Gjoa Haven, NU XOB 1J0

Dear Ms. Beaulieu

RE: 2013 Annual Geotechnical Inspection – Lupin Mine Tailings Containment Area, Nunavut Lupin Mine, Nunavut, License Number 2AM-LUP0914

Please find attached 2013 Geotechnical Inspection Report, completed by SRK Consulting, to fulfil part E, item 6 (g) of our water licence.

There are no issues requiring immediate attention identified in the report. The minor erosional issues, particularly in the perimeter dams, will be addressed in the 2014 summer season. Repairs to the internal Dams M will also be considered. The recommendations regarding inspection locations and schedules will be implemented.

If you have any questions regarding the above, please do not hesitate to contact me.

Sincerely, **Lupin Mines Incorporated.**

George Friesen Manager of Technical Services

CC: Patrick Downey, CEO of Elgin Mining Inc.

2AM-LUP0914

2013 LUPIN GEOTECHNICAL INSPECTION COVER LETTER NOV 5,2013

This file is produced