

Appendix F1

Report: GN Spill Report



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 01-17-2014	REPORT TIME 13:30	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR 01-17-2014	OCCURRENCE TIME 08:00		
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KIOL-BL-14	WATER LICENCE NUMBER (IF APPLICABLE) NWA-2AM-MEA0815		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION MEADOWBANK MINE SITE	REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
E	LATITUDE DEGREES 65 MINUTES 01 SECONDS 19	LONGITUDE DEGREES 96 MINUTES 04 SECONDS 07		
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0X 0A0		
G	ANY CONTRACTOR INVOLVED	CONTRACTOR ADDRESS OR OFFICE LOCATION		
H	PRODUCT SPILLED SODIUM CYANIDE BRIQUETTE	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES ~30KG	U.N. NUMBER 1689	
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER	
I	SPILL SOURCE HCN Storage Box	SPILL CAUSE Punctured box with fork	AREA OF CONTAMINATION IN SQUARE METRES 2 m2	
J	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS Operator was using telehandler try and remove the HCN Box from the seacan, but in the process he punctured one cyanide box. The box ripped and ~30kgs of solid cyanide briquettes dropped onto the base of the seacan and also outside of the sea can onto the ground. Immediately briquettes were safely removed off the ground. No residual cyanide was left outside the sea can, as a skid steer was used to remove the snow in the area of the spill. All of the briquettes and snow were placed in the mixing circuit for use. Agnico Eagle environment department inspected location after the clean up and the area is deemed clean. GPS coordinates for the spill: 14W 0637989 7213945			
L	REPORTED TO SPILL LINE BY JEFFREY PRATT	POSITION ENVIRO COORD	EMPLOYER Agnico Eagle Mines	LOCATION CALLING FROM MEADOWBANK
M	ANY ALTERNATE CONTACT KEVIN BUCK	POSITION ENVIRO SUPERINT	EMPLOYER Agnico Eagle Mines	ALTERNATE CONTACT MEADOWBANK
REPORT LINE USE ONLY				
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN	FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY	CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY				
FIRST SUPPORT AGENCY				
SECOND SUPPORT AGENCY				
THIRD SUPPORT AGENCY				



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 01-22-2014	REPORT TIME 15:30	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR 01-22-2014	OCCURRENCE TIME 08:00			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KIOL-BL-14	WATER LICENCE NUMBER (IF APPLICABLE) NWA-2AM-MEA0815			
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION MEADOWBANK MINE SITE		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
E	LATITUDE DEGREES 65 MINUTES 00 SECONDS 57		LONGITUDE DEGREES 96 MINUTES 04 SECONDS 04		
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0X 0A0			
G	ANY CONTRACTOR INVOLVED	CONTRACTOR ADDRESS OR OFFICE LOCATION			
H	PRODUCT SPILLED RAW SEWAGE	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 200-300 LITERS	U.N. NUMBER N/A		
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
I	SPILL SOURCE SEWAGE TRUCK	SPILL CAUSE VALVE LEFT OPEN	AREA OF CONTAMINATION IN SQUARE METRES 15 SQUARE METERS		
J	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS The operator of the sewage truck left the valve slightly open after checking to see if it was frozen. After he noticed that sewage was spilling on the ground he went to shut it completely. An estimated 200 to 300 liters was spilled on the the ground close to the incinerator area. Operator was met and reminded of operating procedures to prevent any future reoccurrences. Contaminated material was collected and disposed of at the Stormwater management pond. There was no off site impact or discharge to any receiving watercourses.				
L	REPORTED TO SPILL LINE BY ROBIN ALLARD	POSITION ENVIRO SR TECH	EMPLOYER Agnico Eagle Mines	LOCATION CALLING FROM MEADOWBANK	TELEPHONE 8677593555
M	ANY ALTERNATE CONTACT KEVIN BUCK	POSITION ENVIRO SUPERINT	EMPLOYER Agnico Eagle Mines	ALTERNATE CONTACT MEADOWBANK LOCATION	ALTERNATE TELEPHONE 8677634610
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH - DAY - YEAR 04-07-2014	REPORT TIME 16:48	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH - DAY - YEAR 04-06-2014	OCCURRENCE TIME 17:45		
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KIOL-BL-14	WATER LICENCE NUMBER (IF APPLICABLE) NWA-2AM-MEA0815		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION MEADOWBANK MINE SITE		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN	
E	LATITUDE DEGREES 65 MINUTES 01 SECONDS 19		LONGITUDE DEGREES 96 MINUTES 04 SECONDS 07	
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAAKER LAKE X0X 0A0		
G	ANY CONTRACTOR INVOLVED	CONTRACTOR ADDRESS OR OFFICE LOCATION		
H	PRODUCT SPILLED HYDRAULIC OIL	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 340 LITERS	U.N. NUMBER n/a	
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER	
I	SPILL SOURCE BACK HOE HYDRAULIC CYLIND	SPILL CAUSE EQUIPMENT FAILURE	AREA OF CONTAMINATION IN SQUARE METRES 12	
J	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS BACK HOE #6 HAD A FAILURE ON THE HYDRAULIC CYLINDER ON THE STICK OF THE BACK HOE. THE FAILURE CAUSED 340L OF HYDRAULIC OIL TO BE SPILLED IN THE FLOOR OF THE VAULT PIT. OIL WAS PICKED UP WITH ABSORBENT PADS AND PADS TAKEN TO HAZWATSE STORAGE. REMAINDER OF SPILL AND CONTAMINATED ROCK MATERIAL WAS CLEANED OFF THE FLOOR OF PIT BY HEAVY EQUIPMENT. CONTAMINATED MATERIAL WAS TAKEN TO THE MEADOWBANK LANDFARM. GPS LOCATION WILL BE FORWARDED AS A FOLLOW UP. JEFFREY PRATT - (867)759-3555 EXTENSION 6728 / KEVIN BUCK - (867) 763-4610 EXTENSION 6838			
L	REPORTED TO SPILL LINE BY JEFFREY PRATT	POSITION ENVIRO COORDINAT	EMPLOYER AGNICO EAGLE	LOCATION CALLING FROM MEADOWBANK
M	ANY ALTERNATE CONTACT KEVIN BUCK	POSITION ENVIRO SUPERINT	EMPLOYER AGNICO EAGLE	ALTERNATE CONTACT LOCATION MEADOWBANK
REPORT LINE USE ONLY				
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN	
			FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED	
AGENCY	CONTACT NAME		CONTACT TIME	REMARKS
LEAD AGENCY				
FIRST SUPPORT AGENCY				
SECOND SUPPORT AGENCY				
THIRD SUPPORT AGENCY				



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH - DAY - YEAR 05/14/2014		REPORT TIME 09:00		<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER _____
	OCCURRENCE DATE: MONTH - DAY - YEAR 05/13/2014		OCCURRENCE TIME 10:30			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KIOL-BL-14			WATER LICENCE NUMBER (IF APPLICABLE) NWA-2AM-MEA0815		
	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION MEADOWBANK MINE SITE				REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN	
E	LATITUDE DEGREES 65 MINUTES 01 SECONDS 19		LONGITUDE DEGREES 96 MINUTES 04 SECONDS 07			
	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0X 0A0			
G	ANY CONTRACTOR INVOLVED		CONTRACTOR ADDRESS OR OFFICE LOCATION			
	PRODUCT SPILLED Quick Lime (Calcium Carbonate)		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES ~500 kg		U.N. NUMBER	
H	SECOND PRODUCT SPILLED (IF APPLICABLE)		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES		U.N. NUMBER	
	SPILL SOURCE bulk bag		SPILL CAUSE Ripped bag		AREA OF CONTAMINATION IN SQUARE METRES 75	
J	FACTORS AFFECTING SPILL OR RECOVERY		DESCRIBE ANY ASSISTANCE REQUIRED		HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT	
	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS A bulk quick lime bag was ripped during transport. When the zoom boom picked up the bag too move it, the product spilled on the ground from the seacan it was stored in to the point of delivery. Clean up is on going. A FOLOW UP WILL BE PRIOVIDED. GPS LOCATION WILL BE FORWARDED WITH FOLLOW UP. JEFFREY PRATT - (867)759-3555 EXTENSION 6728 / KEVIN BUCK - (867) 763-4610 EXTENSION 6838					
L	REPORTED TO SPILL LINE BY JEFFREY PRATT	POSITION ENVIRO COORDINAT	EMPLOYER AGNICO EAGLE	LOCATION CALLING FROM MEADOWBANK	TELEPHONE 8677593555	
	M	ANY ALTERNATE CONTACT KEVIN BUCK	POSITION ENVIRO SUPERINT	EMPLOYER AGNICO EAGLE	ALTERNATE CONTACT MEADOWBANK LOCATION	ALTERNATE TELEPHONE 8677634610
REPORT LINE USE ONLY						
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130	
	LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS		
LEAD AGENCY						
FIRST SUPPORT AGENCY						
SECOND SUPPORT AGENCY						
THIRD SUPPORT AGENCY						



Follow-up Quick Lime Spill May 13th, 2014

This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-MEA0815, Part H, Item 9c.

Incident

A sea-can containing unusable bag of quick lime, due to their condition, was stored near the tailings pond for disposition into the tailings pond. The zoom boom operator picked up a bag to move it to the disposition point. The bottom of the bag had rotted out and when the bag was lifted out of the seacan the product spilled on the ground. Approximately 500 Kg of quick lime was spilled on the ground. See photo below.

The GPS coordinates for the spill are 65°02'444"W 96°01'115"N.

No water course was affected by this spill.

Clean-up

Site Services cleaned-up contaminated material and soil with the loader and disposed of into the tailings pond.

Preventive measure

In the future, Seacan's full of outdated lime will only be unloaded in a location that prevents any contaminants from reaching the environment. i.e from inside the TSF boundary or on a ramp into the TSF, this way if there is a spill, the material spilt is with the TSF, also any water run off or rain will carry the chemical into the TSF and not the surrounding environment.

Photo's




Photo of spill above; Below spill cleaned up, Lime Seacan Removed, and new seacan for Dewatering supplies in place





Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH - DAY - YEAR 2014-06-03		REPORT TIME 10:30		<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER _____
	OCCURRENCE DATE: MONTH - DAY - YEAR 2014-06-02		OCCURRENCE TIME 10:30			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KIOL-BL-14			WATER LICENCE NUMBER (IF APPLICABLE) NWA-2AM-MEA0815		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION MEADOWBANK MINE SITE			REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
E	LATITUDE DEGREES 65 MINUTES 01 SECONDS 19		LONGITUDE DEGREES 96 MINUTES 04 SECONDS 07			
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0X 0A0			
G	ANY CONTRACTOR INVOLVED		CONTRACTOR ADDRESS OR OFFICE LOCATION			
H	PRODUCT SPILLED CAUSTIC SODA		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 45.4 KG		U.N. NUMBER	
	SECOND PRODUCT SPILLED (IF APPLICABLE)		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES		U.N. NUMBER	
I	SPILL SOURCE BAG		SPILL CAUSE BAGS DROPPED AND BURST		AREA OF CONTAMINATION IN SQUARE METRES 30	
J	FACTORS AFFECTING SPILL OR RECOVERY		DESCRIBE ANY ASSISTANCE REQUIRED		HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS DURING THE MOVEMENT OF A SEACAN CONTAINING CAUSTIC SODA BY THE HYSTER, THE DOOR TO THE SEACAN OPENED AND 5 X 20LB BAGS OF CAUSTIC SODA FELL OUT. THE BAGS BURST OPEN WHEN THEY CONTACTED THE GROUND AS THEY FELL FROM 10-12 FEET. AREA WAS IMMEDIATELY TAPED OFF TO PREVENT ANY ONE FROM GOING THROUGH THE AREA. SPILLED CAUSTIC SODA AND CONTAMINATED SOIL WERE PICKED UP AND TAKEN TO THE TAILINGS POND. UNDERLYING CAUSE WAS THAT THE DOOR WAS NOT INSPECTED PRIOR TO BEING MOVED. DOORS MUST BE SECURELY CLOSED PRIOR TO TRANSPORT. THIS PROCEDURE WILL BE REVIEWED WITH HYSTER OPERATORS. CLEAN UP COMPLETED GPS COORDINATES = 65°01'107"W 96°04'029"N JEFF PRATT - (867)759-3555 EXTENSION 6728 / RYAN VANENGEN - (867) 763-4610 EXTENSION 6838					
L	REPORTED TO SPILL LINE BY JEFFREY PRATT	POSITION ENVIRO COORDINAT	EMPLOYER AGNICO EAGLE	LOCATION CALLING FROM MEADOWBANK	TELEPHONE 8677593555	
M	ANY ALTERNATE CONTACT RYAN VANENGEN	POSITION ENVIRO SUPERINT	EMPLOYER AGNICO EAGLE	ALTERNATE CONTACT MEADOWBANK LOCATION	ALTERNATE TELEPHONE 8677634610	
REPORT LINE USE ONLY						
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130	
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED	
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS		
LEAD AGENCY						
FIRST SUPPORT AGENCY						
SECOND SUPPORT AGENCY						
THIRD SUPPORT AGENCY						



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR July-16-2014	REPORT TIME 09:30	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR July-15-2014	OCCURRENCE TIME 10:00			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KIOL-BL-14	WATER LICENCE NUMBER (IF APPLICABLE) NWA-2AM-MEA0815			
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION MEADOWBANK MINE SITE		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
E	LATITUDE DEGREES 65 MINUTES 01 SECONDS 19		LONGITUDE DEGREES 96 MINUTES 04 SECONDS 07		
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0X 0A0			
G	ANY CONTRACTOR INVOLVED	CONTRACTOR ADDRESS OR OFFICE LOCATION			
H	PRODUCT SPILLED Tailings Slurry	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES ~1 m3	U.N. NUMBER		
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
I	SPILL SOURCE Pipeline	SPILL CAUSE Broken pipeline	AREA OF CONTAMINATION IN SQUARE METRES 10		
J	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS Inside the mill, while mill was operating, the tailings line became disconnected. Before being able to completely stop the mill operation the tailings continued to come out of the pipe. The vast majority of the tailings slurry stayed inside the mill. However, the level became high enough that some leaked outside the door of the mill. Site services department immediately commenced clean up of the slurry. Back hoes were used to mix slurry with rock fill. This material was excavated taken to the Tailings Storage Facility. Photos of clean up and GPS Coordinates will be sent as a follow up. JEFF PRATT - (867)759-3555 EXTENSION 6728 / RYAN VANENGEN - (867) 763-4610 EXTENSION 6838				
L	REPORTED TO SPILL LINE BY JEFFREY PRATT	POSITION ENVIRO COORDINAT	EMPLOYER AGNICO EAGLE	LOCATION CALLING FROM MEADOWBANK	TELEPHONE 8677593555
M	ANY ALTERNATE CONTACT RYAN VANENGEN	POSITION ENVIRO SUPERINT	EMPLOYER AGNICO EAGLE	ALTERNATE CONTACT MEADOWBANK LOCATION	ALTERNATE TELEPHONE 8677634610
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					



July 15th Spill

Please find that following information that is follow up to the Spill report submitted July 16, 2014 by Agnico Eagle Meadowbank division.

Follow-up:

GPS Coordinates: 65°01'114''W 96°07'124''N.

Photos:

Spill:



During Clean up:



Spill area mixed with rock material to absorb



Berm put in place to stop further

After clean up complete:



If you have any other questions please feel free to contact me at your convenience.

Thank you,

Jeff

Jeffrey Pratt
Environmental Coordinator
ICMC Facilitator

jeffrey.pratt@agnicoeagle.com

T: 819.759.3555 x6728
M: 306.960.2370

Agnico Eagle Mines Limited
Meadowbank Division
Baker Lake, Nunavut, Canada
X0C 0A0

agnicoeagle.com



AGNICO EAGLE





Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 08-11-2014	REPORT TIME 10h30	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR 08-10-2014	OCCURRENCE TIME 20h30			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KIOL-BL-14	WATER LICENCE NUMBER (IF APPLICABLE) NWB-2AM-MEA0815			
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION AEM Diesel Refuelling Station in Baker Lake		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
E	LATITUDE DEGREES 64 MINUTES 18 SECONDS 23		LONGITUDE DEGREES 95 MINUTES 56 SECONDS 44		
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0X 0A0			
G	ANY CONTRACTOR INVOLVED ARTIC FUEL	CONTRACTOR ADDRESS OR OFFICE LOCATION BAKER LAKE X0X 0A0			
H	PRODUCT SPILLED DIESEL FUEL	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 200	U.N. NUMBER 1202		
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
I	SPILL SOURCE ARTIC FUEL TRUCK TANK	SPILL CAUSE OVERFLOW	AREA OF CONTAMINATION IN SQUARE METRES 20		
J	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS The truck driver hear a strange sound during the refuelling. He looked and see nothing. By the time he go to stop the pump, diesel fuel goes on the ground. Artic Fuel company advised all of his employees to always shut off the pump in first when they hear or see anything wrong. Spill absorbents were deployed to absorb fuel. Contaminated soil was picked up and will be bring to the Landfarm on the Meadwobank Mine Site.				
L	REPORTED TO SPILL LINE BY Marie-Pier Marcil	POSITION Sr. Compliance Tech	EMPLOYER AGNICO EAGLE	LOCATION CALLING FROM MEADOWBANK	TELEPHONE 8197633700
M	ANY ALTERNATE CONTACT RYAN VANENGEN	POSITION Env. Superintendent	EMPLOYER AGNICO EAGLE	ALTERNATE CONTACT LOCATION MEADOWBANK	ALTERNATE TELEPHONE 8677634610
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY	CONTACT NAME		CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					



August 10, 2014

The following is in follow up to the Reportable Spill which occurred August 10, 2014 at the Meadowbank Gold Project:

- All contaminants from this spill were excavated and removed by equipment or were captured by absorbent pads.
- Excavated materials were hauled to the Meadowbank Landfarm at the Meadowbank Gold Project.
- Absorbents were collected and removed. These absorbents were taken to the Meadowbank Hazardous waste storage area and will be sent south for proper disposal with our annual Hazardous waste shipment.

If you have any other questions please feel free to contact me.

Thank you,

Jeff

Jeffrey Pratt
Environmental Coordinator

ICMC Facilitator

jeffrey.pratt@agnicoeagle.com

T: 819.759.3555 x6728

M: 306.960.2370

Agnico Eagle Mines Limited
Meadowbank Division
Baker Lake, Nunavut, Canada
X0C 0A0

agnicoeagle.com





Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 2014-08-12	REPORT TIME 10h00	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR 2014-08-12	OCCURRENCE TIME 8h00			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KIOL-BL-14	WATER LICENCE NUMBER (IF APPLICABLE) NWB-2AM-MEA0815			
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION MEADOWBANK MINE SITE		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
E	LATITUDE DEGREES 65 MINUTES 1 SECONDS 1	LONGITUDE DEGREES 96 MINUTES 3 SECONDS 53			
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0X 0A0			
G	ANY CONTRACTOR INVOLVED	CONTRACTOR ADDRESS OR OFFICE LOCATION			
H	PRODUCT SPILLED DRILL OIL	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 140	U.N. NUMBER 1270		
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
I	SPILL SOURCE PALLET OF DRILL OIL PAILS	SPILL CAUSE PAIL TIPPED during transport		AREA OF CONTAMINATION IN SQUARE METRES 6	
J	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED		HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS The zoom boom operator was delivering a pallet of drill oil pails with the zoom boom when he hit a bump and 9 pails fell off the pallet. All the contaminated material was cleaned-up and sent to contaminated soil landfarm.				
L	REPORTED TO SPILL LINE BY Marie-Pier Marcil	POSITION Sr. Compliance Tech	EMPLOYER AGNICO EAGLE	LOCATION CALLING FROM MEADOWBANK	TELEPHONE 8197633700
M	ANY ALTERNATE CONTACT Ryan Vanengen	POSITION Env. Superintendent	EMPLOYER AGNICO EAGLE	ALTERNATE CONTACT MEADOWBANK LOCATION	ALTERNATE TELEPHONE 8677634610
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					



AGNICO EAGLE

August 12th, 2014 Spill

Please find the following photos before and after clean-up as a follow up to the Spill report submitted August 12th, 2014 by Agnico Eagle Meadowbank division. All the contaminated material was clean-up and disposed appropriately in the contaminated soil container.

Photos:

Before Clean-up



After Clean-up



If you have any other questions please feel free to contact me at your convenience.

Regards,

Marie-Pier Marcil

Sr. Compliance Technician

marie-pier.marcil@agnicoeagle.com

T: 819.759.3700 x5193

Agnico Eagle Mines Limited
Meadowbank Division
Baker Lake, Nunavut, Canada
X0C 0A0

agnicoeagle.com



AGNICO EAGLE





Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 2014-08-26		REPORT TIME 11h00		<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER _____
	OCCURRENCE DATE: MONTH – DAY – YEAR 2014-08-25		OCCURRENCE TIME 11h00			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KIOL-BL-14			WATER LICENCE NUMBER (IF APPLICABLE) NWB-2AM-MEA0815		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION MEADOWBANK MINE SITE				REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN	
E	LATITUDE DEGREES 65 MINUTES 1 SECONDS 2			LONGITUDE DEGREES 96 MINUTES 3 SECONDS 46		
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0X 0A0			
G	ANY CONTRACTOR INVOLVED		CONTRACTOR ADDRESS OR OFFICE LOCATION			
H	PRODUCT SPILLED Copper Sulfate		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 5 Kg		U.N. NUMBER 3077	
	SECOND PRODUCT SPILLED (IF APPLICABLE)		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES		U.N. NUMBER	
I	SPILL SOURCE 1000 Kg Bag		SPILL CAUSE Damaged bag		AREA OF CONTAMINATION IN SQUARE METRES 1	
J	FACTORS AFFECTING SPILL OR RECOVERY		DESCRIBE ANY ASSISTANCE REQUIRED		HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT	
ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS A sea can containing large bags of copper sulfate was opened in the lay down area, resulting in a spill due to a previously damaged bag. A small amount of copper sulfate in solid form spilled out of the sea can and a small amount spilled onto the ground. A follow-up document including photos before and after clean-up will be send soon. K All the contaminated material was cleaned-up and disposed of in the Tailings Storage Facility.						
L	REPORTED TO SPILL LINE BY Marie-Pier Marcil	POSITION Sr. Compliance Tech	EMPLOYER AGNICO EAGLE	LOCATION CALLING FROM MEADOWBANK	TELEPHONE 8197633700	
M	ANY ALTERNATE CONTACT Ryan Vanengen	POSITION Env. Superintendent	EMPLOYER AGNICO EAGLE	ALTERNATE CONTACT MEADOWBANK LOCATION	ALTERNATE TELEPHONE 8677634610	
REPORT LINE USE ONLY						
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130	
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED	
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS		
LEAD AGENCY						
FIRST SUPPORT AGENCY						
SECOND SUPPORT AGENCY						
THIRD SUPPORT AGENCY						



AGNICO EAGLE

August 25th, 2014 Spill


Please find the following photos before and after clean-up as a follow up to the Spill report submitted August 26th, 2014 by Agnico Eagle Meadowbank division. All the contaminated material was clean-up and disposed appropriately at the tailings storage facility.

Photos:

Before Clean-up



After Clean-up



If you have any other questions please feel free to contact me at your convenience.

Regards,

Marie-Pier Marcil

Sr. Compliance Technician

marie-pier.marcil@agnicoeagle.com

T: 819.759.3700 x5193

Agnico Eagle Mines Limited
Meadowbank Division
Baker Lake, Nunavut, Canada
X0C 0A0

agnicoeagle.com

