

# Construction Progress



# Construction Progress



# Construction Progress



# Construction Progress



# Filter Placement



# Liner Installation



# Liner Installation



# Liner Deployment and Till Compaction at Upstream Toe



# LLDPE Liner Seaming



# Till Placement Above Upstream Liner Toe



# Till Placement Above Upstream Liner Toe



# SD2 Completed



# **SWD 2009 CONSTRUCTION PHOTOS**



**AGNICO EAGLE**

## Submerged Island



## Till Borrow Excavation – Foundation Preparation




## Till Borrow Excavation – Foundation Preparation



**Inflows and  
pumping**



**Culvert  
placement to  
allow for  
dewatering  
during  
construction**



## East Abutment



## West Abutment



## Upstream Cofferdam



## Downstream Cofferdam



# SWD - ROCKFILL PLACEMENT



# SWD – SLOPING OF UPSTREAM SLOPE

Sloping rockfill to 3H:1V



# SWD - BEDDING PLACEMENT

0-150 mm minus material placement and compacted with dozer



# SWD - BEDDING PLACEMENT

0-20mm minus material placement and compaction with excavator bucket, dozer and smooth drum compactor

