



July 4, 2015 Spill

Please find the following information as a follow up to the Spill report submitted February 18th, 2015 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-MEA0815, Part H, Item 9c.

Cause of Spill

After investigation it was found that the weld of the plastic "Y" broke. No significant wear was noted on the piping outside the mill. Movement of the pipe attributed to the failing of the weld.



Spill

All spilled slurry was contained in the tailings line ditch. There was no threat to any receiving waters.

Remediation

Clean up was immediately initiated by shovelling and pumping the slurry back into the leach pad containment. The “Y” that broke was replaced, and tailings deposition recommenced.



Prevention

The Mill maintenance group has added a better support to the location in which the “Y” is located. In addition, as part of the preventative maintenance program, the “Y” will be inspected annually and changed if any irregularities are noted.


Jeffrey Pratt
Environmental Coordinator
ICMC Facilitator

jeffrey.pratt@agnicoeagle.com

T: 819.759.3555 x6728
M: 306.960.2370

Agnico Eagle Mines Limited
Meadowbank Division
Baker Lake, Nunavut, Canada
X0C 0A0

agnicoeagle.com



AGNICO EAGLE

