

Remediation

A vacuum truck was used for approximately an hour to remove the sewage. The ground was frozen so the sewage remained on surface. The ground was clean after the use of the vacuum truck. Electrical cables and pipes are also located in this area, which made clean-up more difficult.



Prevention

The joint was completely taken apart, reinstalled and checked for leaks after reinstallation. It was also inspected frequently on the subsequent days by the STP operator and plumber. The pipe will also be visually checked when it will be completely accessible.



Robin Allard
Environmental - Acting Coordinator
robin.allard@agnicoeagle.com

T: 819.759.3555 x6747

Agnico Eagle Mines Limited
Meadowbank Division
Baker Lake, Nunavut, Canada
X0C 0A0

agnicoeagle.com

