



November 30, 2015 Pit E3 (2015-485)

Please find the following information as a follow up to the Spill report submitted November 30th, 2015 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1525, Part H, Item 8b.

Cause of Spill

Hydraulic hose on backhoe #05 busted while working in pit E3.

Spill/ Remediation

- All contaminants from this spill were excavated and removed by equipment.
- Excavated materials were hauled to the Meadowbank Landfarm. An estimated volume of 20 m³ was removed.

Robin Allard
Environmental - Acting Coordinator
robin.allard@agnicoeagle.com

T: 819.759.3555 x6747

Agnico Eagle Mines Limited
Meadowbank Division
Baker Lake, Nunavut, Canada
X0C 0A0

agnicoeagle.com



AGNICO EAGLE

