



NWB Tools

Ida Porter <ida.porter@nwb-oen.ca>

****Follow up** Reportable Spill at Meadowbank - November 26th, 2015**

Robin Allard <robin.allard@agnicoeagle.com>

Wed, Dec 2, 2015 at 11:11 PM

To: Alain Chouinard <achouinard@gov.nu.ca>, "spills@gov.nt.ca" <spills@gov.nt.ca>, "licensing@nunavutwaterboard.org" <licensing@nunavutwaterboard.org>, "rtoolooktook@gov.nu.ca" <rtoolooktook@gov.nu.ca>, "Christine.Wilson@aandc-aadnc.gc.ca" <Christine.Wilson@aandc-aadnc.gc.ca>, "Justin Hack (Justin.Hack@aandc-aadnc.gc.ca)" <Justin.Hack@aandc-aadnc.gc.ca>, Luis Manzo <dirlands@kivalliqinuit.ca>, Jeff Tulugak <jtulugak@kivalliqinuit.ca>, "Jeff Hart (landsbaker@kivalliqinuit.ca)" <landsbaker@kivalliqinuit.ca>, "Harmer, Rob" <RHarmer@gov.nu.ca>

Cc: Meadowbank Environment <meadowbank.environment@agnicoeagle.com>, Kevin Buck <kevin.buck@agnicoeagle.com>, Jason Allaire <jason.allaire@agnicoeagle.com>, Bertin Paradis <bertin.paradis@agnicoeagle.com>, Dominique Girard <dominique.girard@agnicoeagle.com>

Good evening,

Please find the attached information as a follow up to the Spill report submitted November 26th, 2015 by Agnico Eagle Meadowbank division.

This detailed report is submitted to the Inspectors in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1525, Part H, Item 8c.

If you require further information or have questions, please do not hesitate to contact the undersigned.

Robin Allard
Environmental - Acting Coordinator

robin.allard@agnicoeagle.com

T: 819.759.3555 x6747

Agnico Eagle Mines Limited
Meadowbank Division
Baker Lake, Nunavut, Canada
X0C 0A0

agnicoeagle.com

**AGNICO EAGLE**

From: Robin Allard

Sent: Thursday, November 26, 2015 5:28 PM

To: 'Alain Chouinard'; 'spills@gov.nt.ca'; 'licensing@nunavutwaterboard.org'; 'rtoolooktook@gov.nu.ca'; 'Christine.Wilson@aandc-aadnc.gc.ca'; 'Justin Hack (Justin.Hack@aandc-aadnc.gc.ca)'; 'Luis Manzo'; 'Jeff Tulugak'; 'Jeff Hart (landsbaker@kivalliqinuit.ca)'; 'Harmer, Rob'

Cc: Meadowbank Environment; Kevin Buck; Jason Allaire; Bertin Paradis; Dominique Girard

Subject: Reportable Spill at Meadowbank - November 26th, 2015

Good day,

Attached is a spill report depicting an incident which took place on November 26th, 2015 at Agnico Eagle Mines Ltd., Meadowbank Project.

This spill is being reported as required by the conditions under the Nunavut Water Board License 2AM-MEA1525, Part H, item 8 (b) pursuant to subsection 12(3) of the Nunavut Waters and Nunavut Surface Rights Tribunal Act.

This spill is also being reported as required by the Government of Nunavut's, Environmental Protection Act, paragraph 5.1(a).

A follow up report will be submitted following the cleanup actions.

If you require further information or have questions, please do not hesitate to contact the undersigned.

Robin Allard
Environmental - Acting Coordinator

robin.allard@agnicoeagle.com

T: 819.759.3555 x6744

Agnico Eagle Mines Limited
Meadowbank Division
Baker Lake, Nunavut, Canada
X0C 0A0

agnicoeagle.com



AGNICO EAGLE



3 attachments



December 26, 2015 Vault hydraulic spill

Please find the following information as a follow up to the report submitted November 26, 2015 to the Nunavut Water Board. The information is intended to be reviewed in connection with the ongoing investigation into the hydraulic spill at Meadowbank.

Spill

The spill occurred on November 26, 2015 at the Meadowbank site. The spill was caused by a failure of the vault structure. The spill resulted in the release of approximately 100,000 litres of water into the environment.

Spill

The spill was contained within the vault structure. The spill was contained within the vault structure. The spill was contained within the vault structure.

2015-11-26 Vault hydraulic spill - Follow up_Page_1.jpg

236K



Remediation

The remediation process has commenced. The remediation process has commenced. The remediation process has commenced.

Remediation

The remediation process has commenced. The remediation process has commenced. The remediation process has commenced.

2015-11-26 Vault hydraulic spill - Follow up_Page_2.jpg

131K



2015-11-26 Vault hydraulic spill - Follow up.pdf

250K