

January 24th, 2016 Pit E3

Please find the following information as a follow up to the Spill report submitted January 24th, 2015 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1525, Part H, Item 8c.

Spill Description

On January 24th 2016, a roll-off bin was being brought in pit E3 to collect material. In the process of backing up the truck, the driver hit a rock and punctured the fuel tank. Hole was located at roughly 1/3 of full level of the tank. The quantity of diesel fuel spilled was 150 liters, and the area of contamination 15 m².

There were no off site impact or discharge to any receiving watercourses.

There was an error on the original GPS location mentioned in the report. Spill location was entered as: Northing: 65'04'55" Easting: 95'59'31", it should have been: Northing: 65'00'53" Easting: 96'02'57".

Cause of Spill

Punctured diesel tank due to operator error and conditions of pit area which contains coarser rock material.

Remediation Actions

The area was cleaned and contaminated soil was collected and brought to the Meadowbank landfarm. An estimated volume of 12 m³ of contaminated material was excavated and transported to the landfarm.

The operator of the truck was reminded of backing-up procedures and use of a spotter in unfamiliar conditions.

Closure

We trust that the above details described appropriately the spill incident that occurred at the Meadowbank on January 24th, 2016 and the cleanup activities. Please contact the undersigned should you have any questions.

Robin Allard

Environmental - Acting Coordinator

robin.allard@agnicoeagle.com

T: 819.759.3555 x6747

Agnico Eagle Mines Limited Meadowbank Division Baker Lake, Nunavut, Canada XOC 0A0

agnicoeagle.com



