



NWB Tools

Ida Porter <ida.porter@nwb-oen.ca>

****Follow-up** Reportable Spill at Meadowbank - January 23rd, 2016**

Robin Allard <robin.allard@agnicoeagle.com>

Tue, Jan 26, 2016 at 6:47 PM

To: Erika Voyer <erika.voyer@agnicoeagle.com>, Alain Chouinard <achouinard@gov.nu.ca>, "licensing@nunavutwaterboard.org" <licensing@nunavutwaterboard.org>, "rtoolooktook@gov.nu.ca" <rtoolooktook@gov.nu.ca>, "Christine.Wilson@aandc-aadnc.gc.ca" <Christine.Wilson@aandc-aadnc.gc.ca>, "Justin Hack (Justin.Hack@aandc-aadnc.gc.ca)" <Justin.Hack@aandc-aadnc.gc.ca>, Luis Manzo <dirlands@kivalliqinuit.ca>, Jeff Tulugak <jtulugak@kivalliqinuit.ca>, "Jeff Hart (landsbaker@kivalliqinuit.ca)" <landsbaker@kivalliqinuit.ca>, "Harmer, Rob" <RHarmer@gov.nu.ca>

Cc: Meadowbank Environment <meadowbank.environment@agnicoeagle.com>, Kevin Buck <kevin.buck@agnicoeagle.com>, Jason Allaire <jason.allaire@agnicoeagle.com>, Bertin Paradis <bertin.paradis@agnicoeagle.com>, Dominique Girard <dominique.girard@agnicoeagle.com>, Martin Beausejour <martin.beausejour@agnicoeagle.com>

Good evening,

Please find the attached information as a follow up to the Spill report submitted January 23rd, 2016 by Agnico Eagle Meadowbank division.

This detailed report is submitted to the Inspectors in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1525, Part H, Item 8c.

If you require further information or have questions, please do not hesitate to contact the undersigned.

Robin Allard
Environmental - Acting Coordinator

robin.allard@agnicoeagle.com

T: 819.759.3555 x6744

Agnico Eagle Mines Limited
Meadowbank Division
Baker Lake, Nunavut, Canada
X0C 0A0

agnicoeagle.com

**AGNICO EAGLE**

From: Robin Allard

Sent: Sunday, January 24, 2016 11:33 AM

To: Erika Voyer; 'Alain Chouinard'; 'spills@gov.nt.ca'; 'licensing@nunavutwaterboard.org'; 'rtoolooktook@gov.nu.ca'; 'Christine.Wilson@aandc-aadnc.gc.ca'; 'Justin Hack (Justin.Hack@aandc-aadnc.gc.ca)'; 'Luis Manzo'; 'Jeff Tulugak'; 'Jeff Hart (landsbaker@kivalliqinuit.ca)'; 'Harmer, Rob'

Cc: Meadowbank Environment; Kevin Buck; Jason Allaire; Bertin Paradis; Dominique Girard; Martin Beausejour

Subject: Reportable Spill at Meadowbank - January 23rd, 2016

Hi,

Please find attached a spill report depicting an incident which took place on January 23rd, 2016 at Agnico Eagle Mines Ltd., Meadowbank Project.

This spill is being reported as required by the conditions under the Nunavut Water Board License 2AM-MEA1525, Part H, item 8 (b) pursuant to subsection 12(3) of the Nunavut Waters and Nunavut Surface Rights Tribunal Act.

This spill is also being reported as required by the Government of Nunavut's, Environmental Protection Act, paragraph 5.1(a).

Also, find attached the information as a follow up to the spill report submitted hereby, detailing the clean-up actions. This detailed report is submitted to the Inspectors in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1525, Part H, Item 8c.

If you require further information or have questions, please do not hesitate to contact the undersigned.

Robin Allard
Environmental - Acting Coordinator

robin.allard@agnicoeagle.com

T: 819.759.3555 x6744

Agnico Eagle Mines Limited
Meadowbank Division
Baker Lake, Nunavut, Canada
X0C 0A0

agnicoeagle.com





3 attachments

Forward from Agnico

The attached material was submitted as an addendum to the report on the Meadowbank Spill. It contains information that was not included in the original report.



AGNICO

AGNICO is a leading Canadian mining company. We are committed to safety, environmental stewardship, and community engagement.

AGNICO EAGLE

AGNICO EAGLE

AGNICO EAGLE

AGNICO EAGLE

AGNICO EAGLE

2016-01-23 - Pit E3 Spill - Follow up_Page_2.jpg
188K



January 23rd, 2016, PM 3:30

I have had the following information from the Agnico Eagle team regarding the Meadowbank Spill. This information is being provided to you for your information.

Spill Description

The spill occurred on January 23rd, 2016, at approximately 3:30 PM. It involved a spill of approximately 100 litres of oil from a truck.

The spill occurred on the road between the Meadowbank Spill site and the Meadowbank Spill site. The spill was contained within the spill containment area.

The spill was contained within the spill containment area. The spill was contained within the spill containment area.

The spill was contained within the spill containment area. The spill was contained within the spill containment area.

The spill was contained within the spill containment area. The spill was contained within the spill containment area.

The spill was contained within the spill containment area. The spill was contained within the spill containment area.

The spill was contained within the spill containment area. The spill was contained within the spill containment area.

The spill was contained within the spill containment area. The spill was contained within the spill containment area.

2016-01-23 - Pit E3 Spill - Follow up_Page_1.jpg
259K



Spill of Oil

The spill of oil was contained within the spill containment area. The spill was contained within the spill containment area.



2016-01-23 - Pit E3 Spill - Follow up.pdf
395K