

Remediation Actions

As the sewage was contained in an area enclosed between surrounding roads and the airstrip, and is now frozen, it will be re-assessed in the spring. The water leaving the Sewage Treatment Plant is tested regularly and results meet criteria.

The pipe was fixed and extended further in the pond. As well, snow will not be pushed again on the side of the effluent pipe but rather on the opposite side.

The area was inspected after the repair and no evidence of seeping was found on the north side.



Side blocked for snow



Repaired and extended discharge pipe

Closure

We trust that the above details described appropriately the spill incident that occurred at the Meadowbank on March 12th, 2016 and the cleanup activities. Please contact the undersigned should you have any questions.

Robin Allard
Environmental - Acting Coordinator

robin.allard@agnicoeagle.com

T: 819.759.3555 x6744

Agnico Eagle Mines Limited
Meadowbank Division
Baker Lake, Nunavut, Canada
X0C 0A0
agnicoeagle.com

