

## April 1st, 2016 BAC 11 oil spill

Please find the following information as a follow up to the Spill report submitted April 3rd, 2016 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1525, Part H, Item 8c.

## **Spill Description**

On April 1st, the hydraulic pump on BAC 11 burst and the oil leaked out of the machine.

There were no off site impact or discharge to any receiving watercourses.

Spill location: Northing: 65'04'31" Easting: 95'59'47"



## Cause of Spill

Mechanical failure as the hydraulic pump burst.