

## Cause of Spill

# AGNICO EAGLE

## Remediation Actions

### June 23<sup>rd</sup> Drill #4 Oil spill

Please find the following information as a follow up to the Spill report submitted June 23<sup>rd</sup> 2016 by Agnico Eagle Meadowbank Division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1525, Part H, Item 8c.

### Spill description

On June 23<sup>rd</sup> during operations at Vault pit, a hydraulic hose ruptured on Drill #4 causing oil to be spilled to the ground

There was no off site impacts or discharge to an receiving watercourse

Spill location: Northing 65'04'33" Easting 95'59'98"






## Cause of Spill

Mechanical failure as the hydraulic hose ruptured on the drill

## Remediation Actions


Operator of the drill stopped the equipment immediately to prevent further contamination. Absorbent pads were placed on the ground and a plastic 2ndary containment under the leak. Once the leak was repaired, absorbent pads were picked up and disposed of appropriately and oil collected in the 2ndary containment was placed in a sealed drum and brought to the HAZMAT area to be disposed of appropriately.





## Closure

We trust the above details described appropriately the spill incident that occurred at the Meadowbank site on June 23<sup>rd</sup> 2016 and the cleanup activities. Please contact the undersigned should you have any questions.



Jamie Kataluk

Environment Technician

[Jamie.kataluk@agnicoeagle.com](mailto:Jamie.kataluk@agnicoeagle.com)

Telephone: (867)793-4610 extension 6759

Agnico Eagle Mines Limited

Meadowbank Division

Baker Lake Nunavut, Canada

XOC OAO

**AGNICO EAGLE**

There was no off site impacts or discharge to an receiving watercourse

Spill location: Northing 65°04'33" Easting 95°59'58"

