



November 17th, 2016 Pit E Back hoe 8 oil spill

Please find the following information as a follow up to the Spill report submitted November 18th, 2016 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1525, Part H, Item 8c.

Spill Description

On November 17th, during operation at Pit E3, a hydraulic hose failed on back hoe 8 while mucking ore.

There was no off-site impacts or discharge to any receiving watercourse

Spill location: Northing: 65'00'48" Easting: 96'03'12"

Cause of Spill

The spill was caused by a hose failure

Remediation Actions

All of the oil spilled on ore, which was moved to the Process Plant for processing. No contaminated material was taken to the Landfarm.



Closure

We trust that the above details described appropriately the spill incident that occurred at the Meadowbank on November 17th, 2016 and the cleanup activities. Please contact the undersigned should you have any questions.

A handwritten signature in blue ink, appearing to read "Martin Theriault".

Martin Theriault
Environmental Coordinator

martin.theriault@agnicoeagle.com

T: 819.759.3555 x6744

Agnico Eagle Mines Limited
Meadowbank Division
Baker Lake, Nunavut, Canada
X0C 0A0