



February 25th, 2017 STP Truck spill

Please find the following information as a follow up to the Spill report submitted February 26th, 2017 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1525, Part H, Item 8c.

Spill Description

During the transfer of sewage from the sewage truck to the Sewage Treatment Plan (STP), the transfer hose broke, resulting in sewage spilling on the ground beside the STP.

Spill location: Easting 65'01'20.4" 96'043'11"

There were no off site impact or discharge to any receiving watercourses.



Cause of Spill

The spill was caused by broken transfer hose on the sewage truck.

Remediation Actions

All the contaminated material and snow was excavated, picked up, and taken to the North cell tailings storage facility for disposal.



Corrective measures

The transfer hose was replaced on the sewage truck. It will be visually inspected regularly for possible signs of fatigue and replaced and/or repaired, if necessary.

Closure

We trust that the above details described appropriately the spill incident that occurred at the Meadowbank on February 25th, 2017 and the cleanup activities. Please contact the undersigned should you have any questions.

Robin Allard
Environmental Senior Coordinator
robin.allard@agnicoeagle.com
T: 819.759.3555 x6744
Agnico Eagle Mines Limited
Meadowbank Division

