



## January 28<sup>th</sup>, 2017 LOA 12 oil spill

Please find the following information as a follow up to the Spill report submitted January 29th, 2017 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1525, Part H, Item 8c.

### Spill Description

During operations at Vault, a hydraulic hose failed on Loader 12.

There were no off site impact or discharge to any receiving watercourses.

Spill location: Northing: 65'04'31" Easting: 96'00'32"

### Cause of Spill

Hose failure

### Remediation Actions

Operator of the equipment stopped the engine right away to stop spilling more products on the ground. Operator contacted his supervisor immediately to have the equipment repaired.

All the contaminated material was graded and picked up with a 980 loader and taken to the Landfarm.