



## January 28<sup>th</sup>, 2017 LOA 12 oil spill

Please find the following information as a follow up to the Spill report submitted January 29th, 2017 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1525, Part H, Item 8c.

### Spill Description

During operations at Vault, a hydraulic hose failed on Loader 12

There were no off site impact or discharge to any receiving watercourses.

Spill location: Northing: 65'04'31" Easting: 96'00'32"

### Cause of Spill

Hose failure

### Remediation Actions

Operator of the equipment stopped the engine right away to stop spilling more products on the ground. Operator contacted his supervisor immediately to have the equipment repaired.

All the contaminated material was graded and picked up with a 980 loader and taken to the Landfarm.



## Closure

We trust that the above details described appropriately the spill incident that occurred at the Meadowbank on January 28th, 2017 and the cleanup activities. Please contact the undersigned should you have any questions.

**Martin Theriault**  
**Environmental Technician**

[martin.theriault@agnicoeagle.com](mailto:martin.theriault@agnicoeagle.com)

T: 819.759.3555 x6744

Agnico Eagle Mines Limited

Meadowbank Division

Baker Lake, Nunavut, Canada

X0C 0A0