



## January 29<sup>th</sup>, 2017 HTR 01 fuel spill

Please find the following information as a follow up to the Spill report submitted January 29th, 2017 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1525, Part H, Item 8c.

### Spill Description

After the refueling of the HTR 01, the tanker operator took off the nozzle but fuel came out of the haul truck tank and sprayed on the ground.

There were no off site impact or discharge to any receiving watercourses.

Spill location: Northing: 65'03'46" Easting: 95'59'39"

### Cause of Spill

After investigation, it was observed that the wiggins on the Haul Truck caused the spill.



## Remediation Actions

Investigation was made to identify the cause of the spill. All wiggins were inspected to avoid a second occurrence and information from the supplier was requested. The area was graded and a loader collected the contaminated soil and brought it to the landfarm.

## Closure

We trust that the above details described appropriately the spill incident that occurred at the Meadowbank on January 29th, 2017 and the cleanup activities. Please contact the undersigned should you have any questions.

A handwritten signature in blue ink, appearing to read 'Martin Theriault', is shown on a light yellow background.

**Martin Theriault**  
**Environmental Technician**

[martin.theriault@agnicoeagle.com](mailto:martin.theriault@agnicoeagle.com)

T: 819.759.3555 x6744

Agnico Eagle Mines Limited

Meadowbank Division

Baker Lake, Nunavut, Canada

X0C 0A0