

# April 26<sup>th</sup>, 2017 Portage waste dump HTR 06 spill

Please find the following information as a follow up to the Spill report submitted April 26<sup>th</sup> 2017 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1525, Part H, Item 8c.

### **Spill Description**

During operations at Portage pit waste dump, a hose failure on haul truck 06 occurred creating a spill

Spill location: Easting 65'02'14" 96'03'09"

There were no off site impact or discharge to any receiving watercourses. The distance to the closest lake is estimated at 700 meters.





## Cause of Spill

The spill was caused by a hose failure on the hauling unit.

## **Remediation Actions**

When the operator realized oil was spilling, he stopped the engine and called his supervisor. A grader was used to gather the contaminated soil and a loader collected the material and disposed it at the landfarm





#### Corrective measures

As part of the preventive maintenance program done on site, the hydraulic system including hoses and fittings are inspected. Pre-operations checks including routine visual inspection of the hydraulic system is also performed.

## Closure

We trust that the above details described appropriately the spill incident that occurred at the Meadowbank on April 26<sup>th</sup>, 2017 and the cleanup activities. Please contact the undersigned should you have any questions.

Martin Theriault Environmental Technician

martin.theriault@agnicoeagle.com

T: 819.759.3555 x6759

Agnico Eagle Mines Limited Meadow bank Division Baker Lake, Nunavut, Canada XOC 0A0

agnicoeagle.com



