



March 31ST, 2018 MBK VAULT DUMP 379 COOLANT

GN reference # : 2018-109

Please find the following information as a follow up to the Spill report submitted March 31st 2018 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1525, Part H, Item 8c.

Spill Description

A bearing from the radiator fan has broken. The fan hit the radiator and punctured it. The radiator has emptied from his content. The operator called a mechanic department to repair it.

Spill Location: Northing; 65°05'00.3" Easting: 96° 00'32.3" on IOL

There were no off site impact or discharge to any receiving watercourses. The distance to the closest lake is estimated at 600 meters.



Cause of Spill

The spill was caused when the bearing from the radiator broke and hit the radiator.

Remediation Actions

The equipment was stopped immediately and the maintenance was advised for repairs. All contaminated material was brought to the proper place.



Corrective measures

The coolant system, including hoses, radiator on equipment, is inspected as part of the preventive maintenance program done on site. Pre-operation checks also include visual inspection of the coolant system.

Closure

We trust that the above details described appropriately the spill incident that occurred at the Meadowbank on March 31st 2018 and the cleanup activities. Please contact the undersigned should you have any questions.

Martin Archambault
Environmental Senior Coordinator
martin.archambault@agnicoeagle.com
T: 819.759.3555 x6744
Agnico Eagle Mines Limited
Meadowbank Division
Baker Lake, Nunavut, Canada
X0C 0A0

agnicoeagle.com

