



2019-03-14 MBK 250 Liters Waste Oil Tote

GN reference # : 2019-111

Please find the following information as a follow up to the Spill report (2019-111) submitted March 15th, 2019 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1526, Part H, Item 8c.

Spill Description

During operations at Meadowbank maintenance area, operator was moving a waste oil tote into a sea-can and did not have the forks of the zoom boom lined up properly. The forks punctured the tote and caused to spill inside the sea-can and on the ground.



Location Coordinates of the spill: Northing 65°01'18.4", Easting 96°03'59.6" on IOL

There were no off site impact or discharge to any receiving watercourses. The distance to the closest lake is estimated at 400 meters.

Cause of Spill

Zoom boom forks puncturing the waste oil tote caused the spill.

Remediation Actions

Spill pads were placed on the floor of the sea-can and on the ground, the pads were picked up and brought to the hazmat area and the ground was scraped clean. All the contaminated material was brought to the landfarm.



Corrective measures

Procedure for moving totes was reviewed by warehouse operators which also includes visual inspection of the equipment and work area.

Closure

We trust that the above details described appropriately the spill incident that occurred at the Meadowbank on Mar 14th, 2019 and the cleanup activities. Please contact the undersigned should you have any questions.

Tom Thomson
Environmental Coordinator

tom.thomson@agnicoeagle.com
T: 819.759.3555 x4606744

Agnico Eagle Mines Limited
Meadowbank Division
Baker Lake, Nunavut, Canada
XOC OAO

