



2019-03-08 MBK 260 Liters Hydraulic Oil

GN reference # : 2019-098

Please find the following information as a follow up to the Spill report (2019-098) submitted March 8th, 2019 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1526, Part H, Item 8c.

Spill Description

During operations at Pit E, a hydraulic line on the loader failed causing hydraulic oil to spill on the ground.



Location Coordinates of the spill: Northing 65°00'49", Easting 96°03'11" on IOL

There were no off site impact or discharge to any receiving watercourses. The distance to the closest lake is estimated at 150 meters.

Cause of Spill

Hydraulic line failure on loader

Remediation Actions

Equipment was shut down and maintenance was called to repair the hose. All the contaminated material was scraped up and brought to the landfarm.

Corrective measures

The hydraulic system is inspected as part of the preventive maintenance program done on site. Pre-operation checks also include visual inspection of the equipment.

Closure

We trust that the above details described appropriately the spill incident that occurred at the Meadowbank on Mar 8th, 2019 and the cleanup activities. Please contact the undersigned should you have any questions.



Tom Thomson
Environmental Coordinator

tom.thomson@agnicoeagle.com
T: 819.759.3555 x4606744

Agnico Eagle Mines Limited
Meadowbank Division
Baker Lake, Nunavut, Canada
XOC OAO

