



## 2019-06-26 MBK Mill 1000 Kg Sulfur

GN reference # : 2019-257

Please find the following information as a follow up to the Spill report (2019-257) submitted June 26<sup>th</sup>, 2019 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1526, Part H, Item 8c.

### Spill Description

When the operator has been brought sulfur prill pallets, the bag on the top fell on the ground. The bag punctured and left sulfur on the ground.

Location coordinates of the spill: Northing 65°01'10.7'', Easting 096°04'15.5'' on IOL

There were no off site impact or discharge to any receiving watercourses. The distance to the closest lake is estimated at 150 meters.

### Cause of Spill

The spill was caused by puncture bag when it falls on the ground during the transportation.

### Remediation Actions

Once all the sulfur and contaminated soil have been removed we brought it to the tailings pond.

### Corrective measures

The operators are trained for these tasks. They need to follow the procedure.

## Closure

We trust that the above details described appropriately the spill incident that occurred at the Meadowbank on June 26<sup>th</sup>, 2019 and the cleanup activities. Please contact the undersigned should you have any questions.



**Martin Archambault**  
**Environmental Senior Coordinator**

[martin.archambault@agnicoeagle.com](mailto:martin.archambault@agnicoeagle.com)

T: 819.759.3555 x4606744

Agnico Eagle Mines Limited  
Meadowbank Division  
Baker Lake, Nunavut, Canada  
XOC OAO

