



2019-09-05 MBK SO2 Plant 40 kg Sulfur Prills

GN reference # : 2019-367

Please find the following information as a follow up to the Spill report (2019-367) submitted September 6th 2019 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1526, Part H, Item 8c.

Spill Description

Sea container was delivered with damaged bags of sulphur prills. Workers were trying to salvage bags but as they removed them some pallets and bags scraped some spillage out on the ground at the entrance of the container.

Location coordinates of the spill: Northing 65°01'10.7'', Easting 096°04'15.5'' on IOL

There were no off site impact or discharge to any receiving watercourses. The distance to the closest lake is estimated at 220 meters.



Cause of Spill

The spill was caused by a human error when the operator during the operation.

Remediation Actions

Once all the sulfur and contaminated soil have been removed we brought it to the tailings pond.

Corrective measures

The operators are trained for these tasks. They need to follow the procedure.



Closure

We trust that the above details described appropriately the spill incident that occurred at the Meadowbank on September 5th, 2019 and the cleanup activities. Please contact the undersigned should you have any questions.

Martin Archambault
Environmental Senior Coordinator

martin.archambault@agnicoeagle.com
T: 819.759.3555 x4606744

Agnico Eagle Mines Limited
Meadowbank Division
Baker Lake, Nunavut, Canada
XOC OAO

