

# 2021-06-16 MBK Diesel Fuel

GN reference #: 2021-250

Please find the following information as a follow up to the Spill report submitted June 17, 2021 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1530, Part H, Item 8c.

## **Spill Description**

During a routine inspection, a small presence (10m²) of diesel fuel was observed in the secondary containment of the Meadowbank Fuel Tank. Further investigation has failed to demonstrate any new inflow of fuel in the secondary containment. No conclusion has come to as the origin of the fuel. The spill report was communicated in the spirit of transparency, and by due diligence, as the fuel is fully contained within the secondary containment.



Spill location: 65'00'57.1" 96'03'55.4" on IOL.

There were no off site impacts or discharge to any receiving watercourses. Distance to the closest water body is 250 meters to Third Portage Lake.

## Cause of Spill

It is currently unknown what is the origin or the source of the spill. The fuel tank is not expected to have been the source of the small presence of fuel, but rather the potential temporary

## **Remediation Actions**

The main fuel tank has been emptied, and is in the process of being inspected and will be recertified.

#### Corrective measures

Any potential deficiency identified in the inspection process of the fuel reservoir will be addressed and corrected to recertify the tank.

#### <u>Closure</u>

We trust that the above details described appropriately the spill incident that was observed at the Meadowbank site on June 16, 2021 and the cleanup activities. Please contact the undersigned should you have any questions.



Eric Haley | Environmental Coordinator
eric.haley@agnicoeagle.com | Direct 819.759.3555 x4606744 |
Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada X0C 0A0
agnicoeagle.com